




BANK FAILURE DO TO
EROSIONAL MECHANISMS



BANK FAILURE DO TO
EROSIONAL MECHANISMS

	<p>U.S. ARMY ENGINEER DISTRICT, ST. LOUIS CORPS OF ENGINEERS ST. LOUIS, MO</p>	
<p>PREPARED BY: M. RODGERS CHECKED BY: R. DAVINROY</p> 	<p>KASKASKIA RIVER BANK EROSION STUDY</p> <p><u>BANK EROSION OTTER BRANCH CREEK</u></p>	
	<p>Plot Date: 9/02</p>	<p>PLATE NO. 9</p>