EXAMPLES OF A WELL COMPLETED RFA (REQUEST FOR ASSISTANCE)

Examples for Completing a RFA (Request for Assistance)

Sketch in levee, giving top width and approximate height for each section. Show approximate location of all damage and approximate quantities required to repair. Show Section, Township. and Range numbers or other identifier. Show Streams and lakes; show any connecting levees on adjacent property.

SECTION 36 TOWNSHIP 38 N RANGE 10 E

North Leroe by Port. 1900 of washed out Level with Large scour hole.

Lower Mitchell Level 400' of washedout Level with large scour hole.

Level connecting with Kaskaskia Level 1'To 3" of rock and dirt washed off Top of Level, 800'

Level along Hay 61 400' washed top 1'To 5' off. Shede on side of Level east of Maring bridge 200'

Shede on side of Levre east of Marina bridge 150'

G Ware wash on side of Level 3500'


H Road stone washed off top of Level 3.5 miles

I Erosion at tow of Levee 300

Estimated Yearly Value of Crops:

County		
Waterway causing flood:		
Date and Result of Last Inspection:		
Repair Required: Total Length:		
No. of Acres Protected by Levee:		

2015 PL84-99 - Ste. Genevieve Drainage and Levee District




SECTION TOWNSHIP RANGE

A	. Riverside of Leve has thin or no sod cover
• • •	DETWEEN MAP STATTIONS 120+00 and 545+00
h,	Top of have is more entrep NEAR LEVER
	STATION 120 too FOR APPROXIMATELY 500 FT
	from SANDBAGGING EFFORTS
С.	SINKHOLE ABOVE PUMPSTATION DISCHARGE PIPE

County	State
Waterway causing flood:	
Date and Result of Last Inspection:	
Repair Required: Total Length:	
No. of Acres Protected by Levee:	
Estimated Yearly Value of Crops:	

Illinois River Flood Fight Maps - 2009-2015 Data





COMPUTED BY DATE PROJECT Page _ of _ BY DATE CHECKED SUBJECT BREACH/TYPE 3 TYPE I/WAVE WASH

			Crown			Center	rter	
Appoximate	e		Removal		Length	Coordinates	inates	Additional
Station	Damage	Туре	Required	RS/LS	(ft)	Lat	Long	Info
947+00	Slide	Toe	92	RS	45	37.693128 89.438717	89.438717	
00+096	Slide	Foe	2	ភ	75	37,696581	89.437834	89.437834 Gravity drain structure within slide area
965+00	Slide	Surface	5	LS	20	37.697966 89.437646	89,437646	-
00+896	Slide	Toe	yes	RS	85	37.698460 89.437641	89.437641	
970+00	Slide	Toe	yes	ম	75	37.700095	89,437492	
980+00	Siide	Toe	yes	SI	85	37.702684	89,437639	
00+066	Slide	Surface	yes	rs Si	35	37.704963	89.437753	
1011+00	Siide	Toe	yes	LS/RS	90/160	37.709305	89.437815	89.437815 Slides on both sides of levee
1013+00	Slide	Toe	yes	SI	8	37.710127	89,437815	
1017+00	Slide	Toe	ဍ	RS	230	37,713210 89,435036	89,435036	
1027+00	Slide	Toe	yes	S	8	37.713581 89.434330	89.434330	
1027+50	Slide	Toe	yes	S3	185	37.713707	89,433951	
1041+00	Slide	Toe	yes	27	70	37.714937 89.430279	89.430279	
1042+50	Pipe Failure					37.715261	89.429414	37.715261 89.429414 Large depression in berm directly behind GD Str
1055+00	Slide	Toe	yes	RS	7.5	37.716462 89.426164	89.426164	
1061+00	Slide	Toe	or.	RS	55	37.717350 89.423218	89.423218	
1195+00	Slide	Toe	No	S	20	37.749077	89.446097	37.749077 89.446097 Back levee close to Grimsby - North of powerlin
67.	1 2 1			-	;			
442+00	Side	Surface		S	52	37.747891	89.612000	37.747891 89.612000 Main line levee
265+00	Slide	Toe	01	SS.	110	37.767811	89.658828	37.767811 89.658828 Main line levee

SECTION 36 TOWNSHIP 12 N I	RANGE	13W
----------------------------	-------	-----


		€-10ft	\rightarrow	
* wave wash	<u>→</u>			
Á		54a <u> </u>	to	1200 tt

*No survey but approx. quantities are:


Fill/scour repair: 250 to 500 cu. yds

seeding: 0.5 to 1.0 acres

County			
Waterway c	ā		
Date and Re			
Repair Requ	1		
No. of Acres	S		
Estimated Y			



SECTION _____TOWNSHIP 48N RANGE 6E



Note: Exact damage was estimated and measured by Project Engineers Patrick VanDeWiele and Brittany Saulnier

