




# Navigation Channel Condition Status Report - October 17, 2018



**Dredge Status:**

**Dredge Potter:** On standby pending lower Mississippi River levels.

**Dredge Goetz:** TBD, pending river levels.

**Channel Marker Status:**

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

**Pathfinder:** The Pathfinder is dockside.

**Additional Risks / Concerns**

**Navigation Notices**

**Local Notice to Mariners**

The Upper Mississippi and Illinois River are in high water action phase. Please see the USCG Local Notice to Mariners for more information. [Link to notice](#)

**Weather**

Highs in the mid 50s to mid 60s, lows from the low 30s to upper 40s. Chance of rain to the south on Friday.

**Hannibal, MO**

**St. Louis, MO**

**Cape Girardeau, MO**

**Cairo, IL**

**Web Information**

For additional River Training Structure information, see the links below:

**Current Construction**

**Recently Completed Construction**

For open Regulatory Public Notices, See the link below:

**Regulatory Public Notices**

For the most recent channel patrol and pre or post dredge surveys, see the links below:

**Channel Patrol Surveys**

**Dredge Surveys**

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

**Electronic Charts**

**More Status Reports**

**Click for older status reports**

| Key:   |                                | Probable Dredge Areas |                 |            |                 |        |
|--|--------------------------------|-----------------------|-----------------|------------|-----------------|--------|
|  |                                | River Mile            | Problematic On: | Dredge ETA | Dredge Complete | Dredge |
| ⊕  | Current Construction Location  | 167-173               |                 | TBD        |                 | Potter |
| ◆  | Anticipated Dredging Locations |                       |                 |            |                 |        |
| ☆  | Groundings                     |                       |                 |            |                 |        |
| △  | Dredge Potter                  |                       |                 |            |                 |        |
| ○  | Fisher                         |                       |                 |            |                 |        |
| ▽  | Dredge Goetz                   |                       |                 |            |                 |        |
| Very Likely to be Problematic at Low Water   |                                |                       |                 |            |                 |        |
| Could be Problematic at Low Water  |                                |                       |                 |            |                 |        |
| Problem Resolved/Not Problematic   |                                |                       |                 |            |                 |        |
| Please email comments or suggestions to <a href="mailto:mvsnavstatus@usace.army.mil">mvsnavstatus@usace.army.mil</a> |                                |                       |                 |            |                 |        |