


# Navigation Channel Condition Status Report - May 27, 2020



**Dredge Status:**

**Dredge Potter:** Dockside at Service Base.

**Channel Marker Status:**

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

**Pathfinder:** The Pathfinder is dockside this week and next.

**Additional Risks / Concerns**

**Navigation Notices**

**Local Notice to Mariners**

There are advisories for the Miss. and IL Rivers for HIGH RIVER STAGES. Find them [here](#). Buoys may be missing due to high water.

**Weather**

Highs from the low 70s to the upper 80s, lows from the low 50s to the low 70s. Thunderstorms Thursday with some additional storms to the south on Friday.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

**Web Information**

For additional River Training Structure information, see the links below:

**Current Construction**

**Recently Completed Construction**

For open Regulatory Public Notices, See the link below:

**Regulatory Public Notices**

For the most recent channel patrol and pre or post dredge surveys, see the links below:

**Channel Patrol Surveys**

**Dredge Surveys**

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

**Electronic Charts**

**More Status Reports**

**Click for older status reports**

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location	241.4	End of June	Pending		Potter
◆	Anticipated Dredging Locations					
☆	Groundings					
△	Dredge Potter					
▽	Dredge Goetz					
○	Dredge Bill Holman					
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						
Please email comments or suggestions to <a href="mailto:dawn.lamm@usace.army.mil">dawn.lamm@usace.army.mil</a>						