




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - December 04, 2019



Dredge Status:

Dredge Potter: Docksides.
Dredge Bill Holman: TBD based upon river levels.

Channel Marker Status:

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.
Pathfinder: Running an IL River channel patrol next week.

Additional Risks / Concerns

Navigation Notices
Local Notice to Mariners
Shoaling, off station buoys and drift has been reported at a number of locations in the pools and lower river (beyond what is shown). Please review the Notice to Mariners here for more info.

Weather

Highs from the low 50s to the high 50s, lows from the high 20s to the mid 30s. Chance of rain Thursday, Sunday, and Monday.
Hannibal, MO
St. Louis, MO
Cape Girardeau, MO
Cairo, IL

Web Information

For additional River Training Structure information, see the links below:
Current Construction
Recently Completed Construction
For open Regulatory Public Notices, See the link below:
Regulatory Public Notices
For the most recent channel patrol and pre or post dredge surveys, see the links below:
Channel Patrol Surveys
Dredge Surveys
Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:
Electronic Charts

More Status Reports

Click for older status reports

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location	SEMO Port		TBD	TBD	Bill Holman
◆	Anticipated Dredging Locations	Kasky RM 1		TBD	TBD	Bill Holman
☆	Groundings					
△	Dredge Potter					
▽	Dredge Goetz					
○	Dredge Bill Holman					
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						
Please email comments or suggestions to mvsnavstatus@usace.army.mil						