




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - January 15, 2020



Dredge Status:

Dredge Potter: Currently Dockside due to High Water

Dredge Bill Holman: Currently on hold due to High Water.

Channel Marker Status:

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

Pathfinder: Dockside over the next week.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

Weather

Highs from the mid teens to the upper 50s, lows from the single digits to the low 40s. High probability of snow/ice to the north and rain to the south Friday into Saturday.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the links below:

Current Construction

Recently Completed Construction

For open Regulatory Public Notices, See the link below:

Regulatory Public Notices

For the most recent channel patrol and pre or post dredge surveys, see the links below:

Channel Patrol Surveys

Dredge Surveys

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

Electronic Charts

More Status Reports

Click for older status reports

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location	171.0		TBD	TBD	Potter
⊕	Anticipated Dredging Locations	170.0		TBD	TBD	Potter
☆	Groundings	147.7		TBD	TBD	Potter
△	Dredge Potter	177.5		TBD	TBD	Potter
○	Dredge Bill Holman					
▽	Dredge Goetz					
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						
Please email comments or suggestions to mvsnavstatus@usace.army.mil		SEMO Port		TBD	TBD	Bill Holman
		Kasky RM 1		TBD	TBD	Bill Holman