




St. Louis District



Dredge Potter: Dredging operations suspended, major maintenance being performed.

Mechanical Dredge: Demobilized.

Dredge Goetz: Demobilized out of district.

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution. For ATON or Buoy issues please contact or 319-520-8556 SUMRWaterways@usca.mil.

Pathfinder: Docksider

Navigation Notices

Local Notice to Mariners

Weather

Highs from the lower 80s to the lower 50s, lows from the upper 50s to the mid 30s. Storms and high wind on Friday. Chance of rain to the South on Saturday.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the links below:

Current Construction

Recently Completed Construction

For open Regulatory Public Notices,
See the link below:

Regulatory Public Notices

For the most recent channel patrol and pre or post dredge surveys, see the links below:

Channel Patrol Surveys

Dredge Surveys

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

Electronic Charts

More Status Reports

[Click for older status reports](#)

Key:		Probable Dredge Areas (9 ft DEPTH)				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location					
◆	Anticipated Dredging Locations					
☆	Groundings	➤	Mechanical			
△	Dredge Potter	⬡	Dredge Goetz			
▽	Dredge Bill Holman	⬢	Dredge Hurley			
	Very Likely to be Problematic at Low Water					
	Could be Problematic at Low Water					
	Problem Resolved/Not Problematic					
Please email comments or suggestions to dawn.lamm@usace.army.mil						