




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - 30 March 2016



Dredge Status:
Dredge Potter: Dockside until further notice.

Channel Marker Status:
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.
The Pathfinder will be dockside next week.

Additional Risks / Concerns
Navigation Notices
Local Notice to Mariners

Weather
Highs in the mid 70's; Lows in the lower 40's, rain Wed., and Thurs.
Hannibal, MO
St. Louis, MO
Cape Girardeau, MO
Cairo, IL

Web Information
For additional River Training Structure information, see the link below:
<http://www.mvs.usace.army.mil/Mission/Navigation/Construction/Current.aspx>
For the most recent channel patrol and pre-dredge surveys, see the link below:
<http://www.mvs.usace.army.mil/Mission/Navigation/Surveys/ChannelPatrol.aspx>
The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:
<http://www2.mvr.usace.army.mil/NIC2/>

More Status Reports
Click for older status reports

Key:

- ◆ Anticipated Dredging Locations
- ☆ Groundings
- △ Dredge Potter
- ▽ Dredge Goetz

Very Likely to be Problematic at Low Water
Could be Problematic at Low Water
Problem Resolved

Probable "Hot" Spots

River Mile	Min Depth at Low Water	Problematic On:	Dredge ETA	Dredge Complete	Dredge

Please email comments or suggestions to mvsnavstatus@usace.army.mil