




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - 10 May 2017



Dredge Status:
Dredge Potter: Docksides

Channel Marker Status:
Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.
For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.
Pathfinder: The Pathfinder is docksides this week.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

Zones of the Upper Miss. and Ill. are in either the high water watch or recovery phase IAW the Western Rivers WAP Annex. Please see the Local Notice to Mariners (Link) for more information.

Weather
Highs in the Mid 60s to mid 80s. Lows in the low 50s to upper 60s. Storms Thursday and Friday to the south. Otherwise partly cloudy to sunny.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the links below:

Current Construction

Recently Completed Construction

For open Regulatory Public Notices, See the link below:

Regulatory Public Notices

For the most recent channel patrol and pre or post dredge surveys, see the links below:

Channel Patrol Surveys

Dredge Surveys

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

Electronic Charts

More Status Reports

Click for older status reports

Key:

- ⊕ Current Construction Location
- ◆ Anticipated Dredging Locations
- ☆ Groundings
- △ Dredge Potter
- ▽ Dredge Goetz

Very Likely to be Problematic at Low Water
Could be Problematic at Low Water
Problem Resolved/Not Problematic at this time

Probable Dredge Areas

River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge

Please email comments or suggestions to mvsnavstatus@usace.army.mil