

ACTIVITY HAZARDS ANALYSIS

Date Prepared: February 4, 2010

Project: EC-HMQ

Prepared By: Karen M. González

Job: Cleaning/Installing Orifice Lines

Reviewed By: Michael Henry

Risk Assessment Code(RAC):

E

E = Extremely High Risk
 H = High Risk
 M = Moderate Risk
 L = Low Risk

		P r o b a b i l i t y				
		Frequent	Likely	Occasional	Seldom	Unlikely
S e v e r i t y	Catastrophic	E	E	H	H	M
	Critical	E	H	H	M	L
	Marginal	H	M	M	L	L
	Negligible	M	L	L	L	L

Recommended Protective Clothing & Equipment:

Restraint, positioning or personal arrest devices (i.e. lanyard and lifelines)
 Warning systems (i.e. alarms, warning lines and signs)
 PFD's, gloves, waders ets...
Frequent, Catastrophic

JOB STEPS	HAZARDS	ACTIONS TO ELEMIMATE OR MINIMIZE HAZARDS	EM 385-1-1 (PARA REF)
Cleaning/Installing Orifice Lines	Bodily injury or death	<ol style="list-style-type: none"> 1. Notify office that you are going to a site. Use the proper procedure (i.e., time of departure, destination). 2. Call office upon departure (i.e., type of work, approximate time of return). 3. Wear proper gear (chest waders, gloves, PFD if necessary etc.) 4. Care should be taken when entering or exiting the water to lessen the chances of losing balance 	Section 21 *Section 21.A.1.a *Section 21.A.1.b *Section 21.A.1.e