




Navigation Channel Condition Status Report - 30 May 2013



Dredge Status

Dredge Potter
- Dockside

Channel Marker Status

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

The Pathfinder is dockside for maintenance this week..

Additional Risks / Concerns

- Navigation Notices
- Local Notice to Mariners

Current Weather

Highs in the low 90s to the high 60s; lows in the low 70s to mid 50s. Chance of rain Wednesday until Saturday.
[Hannibal, MO](#)
[St. Louis, MO](#)
[Cape Girardeau, MO](#)
[Cairo, IL](#)

Web Information

For additional info about New River Training Structures, see the link below:
<http://www.mvs.usace.army.mil/Missions/Navigation/Construction.aspx>

For the most recent channel patrol and predredge surveys, see the link below:
<http://www.mvs.usace.army.mil/Missions/Navigation/Surveys.aspx>

The new electronic Navigation charts for the Upper Mississippi River are now available online for download or to order at the below link:
<http://www2.mvr.usace.army.mil/NIC2/mrcharts.cfm>

More Status Report

Please click for older status reports

MILE 206.0 - AID TO NAVIGATION
A can buoy has been reported not properly marking the channel and partially submerged in the vicinity of Mile 206.0. Transit with caution.

MILE 171.0 - SUNKEN BARGE
A sunken barge has been reported in the vicinity of Mile 171.0, Norte Dame Fleet Nr. 3. The barge is reportedly marked with a lighted white buoy. Mariners are urged to transit the bridge with caution.

Key	
◆	Anticipated Dredging Locations
★	Groundings
▲	Dredge Potter
▼	Dredge Hurley
▽	Dredge America
Red	Very Likely to be Problematic at Low Water
Yellow	Could be Problematic at Low Water
Green	Problem Resolved

Probable "Hot" Spots Within 4 Weeks				
River Mile	Estimated Problematic Date	Dredge ETA	Dredge Complete	Dredge

Please click below to email comments or suggestions:
mvsnavstatus@usace.army.mil