




Navigation Channel Condition Status Report - January 30, 2019



Dredge Status:

Dredge Potter: Suspended due to frigid temperatures.

Dredge Goetz: Suspended due to frigid temperatures.

Channel Marker Status:

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

Pathfinder The Pathfinder is dockside this week and next.

Additional Risks / Concerns

Navigation Notices

Local Notice to Mariners

Weather

Highs from zero to the low 60s, lows from the negative mid single digits to the mid 50s. Chance of precipitation scattered through the week.

Hannibal, MO

St. Louis, MO

Cape Girardeau, MO

Cairo, IL

Web Information

For additional River Training Structure information, see the links below:

Current Construction

Recently Completed Construction

For open Regulatory Public Notices, See the link below:

Regulatory Public Notices

For the most recent channel patrol and pre or post dredge surveys, see the links below:

Channel Patrol Surveys

Dredge Surveys

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

Electronic Charts

More Status Reports

Click for older status reports

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location	184		-		Goetz
◆	Anticipated Dredging Locations	Kaskaskia		TBD		Goetz
☆	Groundings	171.0		-		Potter
△	Dredge Potter	173.0		TBD		Potter
▽	Dredge Goetz	168.0		TBD		Potter
○	Fisher	169.0		TBD		Potter
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						

Please email comments or suggestions to mvsnavstatus@usace.army.mil