




US Army Corps of Engineers
St. Louis District

Navigation Channel Condition Status Report - January 29, 2020



Dredge Status:

Dredge Potter: Currently Dockside due to High Water

Dredge Bill Holman: Due to start dredging at SEMO Port on 2/1/20.

Channel Marker Status:

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

Pathfinder: The Pathfinder is currently running a lower river channel patrol and will be dockside next week.

Additional Risks / Concerns

- Navigation Notices
- Local Notice to Mariners

Weather

Highs from the low 30s to the low 60s, lows from the mid 20s to the low 50s. Chance of snow/rain today and partly cloudy to sunny over the next week.

- Hannibal, MO
- St. Louis, MO
- Cape Girardeau, MO
- Cairo, IL

Web Information

- For additional River Training Structure information, see the links below:
- Current Construction
 - Recently Completed Construction
- For open Regulatory Public Notices, See the link below:
- Regulatory Public Notices
- For the most recent channel patrol and pre or post dredge surveys, see the links below:
- Channel Patrol Surveys
 - Dredge Surveys
- Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:
- Electronic Charts

More Status Reports

[Click for older status reports](#)

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location	SEMO Port		1-Feb	5-Feb	Bill Holman
◆	Anticipated Dredging Locations	Kasky RM 1		7-Feb	15-Feb	Bill Holman
☆	Groundings					
△	Dredge Potter					
○	Dredge Bill Holman					
▽	Dredge Goetz					
Very Likely to be Problematic at Low Water						
Could be Problematic at Low Water						
Problem Resolved/Not Problematic						
Please email comments or suggestions to mvsnavstatus@usace.army.mil						