


## Navigation Channel Condition Status Report - April 15, 2020



**Dredge Status:**

**Dredge Potter:** In dry dock for maintenance and repairs.

**Channel Marker Status:**

Be aware that there may be other buoys off station/missing than the ones mentioned in this report. Mariners should use caution.

For ATON or Buoy issues please contact SUMRWaterways@uscg.mil or 319-520-8556.

**Pathfinder:** The Pathfinder will be dockside this week and will run an Illinois River channel patrol next week.

**Additional Risks / Concerns**

**Navigation Notices**

**Local Notice to Mariners**

There are advisories for the Miss. and IL Rivers for HIGH RIVER STAGES. Find them [here](#). Buoys may be missing due to high water.

**Weather**

Highs from the high 40s to the mid 70s, lows from the low 30s to the mid 50s. Chance of rain Thursday and Friday to the north and Friday and Saturday to the south.

**Hannibal, MO**

**St. Louis, MO**

**Cape Girardeau, MO**

**Cairo, IL**

**Web Information**

For additional River Training Structure information, see the links below:

**Current Construction**

**Recently Completed Construction**

For open Regulatory Public Notices, See the link below:

**Regulatory Public Notices**

For the most recent channel patrol and pre or post dredge surveys, see the links below:

**Channel Patrol Surveys**

**Dredge Surveys**

Electronic Navigation charts for the Upper Mississippi River are available online for download or to order at the below link:

**Electronic Charts**

**More Status Reports**

**Click for older status reports**

Key:		Probable Dredge Areas				
		River Mile	Problematic On:	Dredge ETA	Dredge Complete	Dredge
⊕	Current Construction Location					
◆	Anticipated Dredging Locations					
☆	Groundings					
△	Dredge Potter					
▽	Dredge Goetz					
○	Dredge Bill Holman					
	<b>Very Likely to be Problematic at Low Water</b>					
	<b>Could be Problematic at Low Water</b>					
	<b>Problem Resolved/Not Problematic</b>					
<a href="mailto:dawn.lamm@usace.army.mil">Please email comments or suggestions to dawn.lamm@usace.army.mil</a>						