


7

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164213	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 196 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Chuck Finkenbain / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865338 N 1075785			
9. SURFACE ELEVATION N/A		10. DATE STARTED 2/27/14			
11. DATE COMPLETED 2/27/14		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR		24. LOCATION SKETCH/COMMENTS			

LOCATION SKETCH/COMMENTS: COC #: LE02272014-054

SCALE: None



Recorded By J. Neutzling Date 2/27/14 QA By [Signature] Date 3-3-14

8

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER 196 FPS		SVP 164213		SHEET 2 of 2	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		449 NAI			
USCS		Depth (ft bgs)		Description of Materials		449 NAI	
54		6067		Clayey SILT, brown, little to some v. fine sand, low plasticity, moist - ML		SVP164213 1043 Iso Th gamma spec	
64		5984				1044	
63		6081				SVP164214 1047 Iso Th gamma spec	
50		5779				Archived 1081 Iso Th gamma spec	
Borehole terminated						(soil)	

Recorded By J. Neutzling Date 2/27/14 QA By [Signature] Date 3-3-14

9

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 164207	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION: #194 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER Chuck Finkenbein / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865280 N 1075684			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 E - 42cpm		10. DATE STARTED: 2/27/14		11. DATE COMPLETED 2/27/14	
44-10 C - 5488cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES: N/A					
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		SCALE: None			
LOCATION SKETCH/COMMENTS and soil plug 2/27/14 COC #: LE02272014-05H					

Recorded By J. Neutzling Date 2/27/14 QA By [Signature] Date 3-3-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 194 FPS
SVP 164207

PROJECT Coldwater Creek		INSPECTOR: J. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silt, brown, little to some v. fine sandy, little clay, low plasticity, moist w/ trace of brick - ML (Fill)	65			SVP164207 1059 Iso Th gamma spec		
	1		5798					
	2		66			SVP164208 1101 Iso Th gamma spec		
	3		6114					
	4		59			1103		
	5		6200					
	6	trace of brick	51			1106		
	7		5965					
	8	Clayey SILT, brown, little very fine sandy, low plasticity, moist - ML	55			1111		more clayey but still silty
	9		6249					
	10		59			1114		looks reddish brown (glasser) but w/o glasses yellow brown.
	11		6091					
	12		46			1117		
	13		6280					
	14		57			SVP164209 1120 Iso Th gamma spec		
	15		6182					
	16	Silty CLAY, brown mottled by gray, little v. fine sandy, low plasticity, moist - CL	54			1125		more clay
	17		6331					
	18		49			1130		
	19		6317					
	20		58			SVP164210 1181 Iso Th gamma spec		
	21		5914					
	22		52			1182 Iso Th gamma spec		
	23		6756					
	24	Borehole terminated						soil

Recorded By J. Neutzling Date 2/27/14 QA By [Signature] Date 3-3-14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164215	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 197 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER Chuck Finkenbein/Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865222 N1075785			
9. SURFACE ELEVATION N/A		10. DATE STARTED: 2/27/14			
11. DATE COMPLETED 2/27/14		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs.		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR		24. LOCATION SKETCH/COMMENTS			
Backfill using bentonite		Backfill using bentonite			
LOCATION SKETCH/COMMENTS		SCALE: None			

Recorded By G. Neutzing Date 2/27/14 QA By T. [Signature] Date 3-3-14

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER 197 FPS	
PROJECT Coldwater Creek		INSPECTOR: G. Neutzing	
SHEET 2 of 2		SVP164215	
USCS	Depth (ft bgs)	Description of Materials	Remarks
0	0	Silty CLAY, brown, little v. fine sand, little gravel & asphalt pieces, low plasticity, moist - CL	
1	0.5		
2	1.0		
3	1.5		
4	2.0	Borehole terminated	
5			
6			
7			
8			
9			
10			

Recorded By G. Neutzing Date 2/27/14 QA By T. [Signature] Date 3-3-14

13

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP164229	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 204 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Chuck Finkenbain / Adam Green		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E. 865280 N 1075886			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 E - 34 cpm		10. DATE STARTED: 2/27/14		11. DATE COMPLETED: 2/27/14	
44-10 C - 5206 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES: N/A					
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
21. TOTAL CORE RECOVERY: N/A		RAD SAMPLES		QA/QC SAMPLES	
		2		0	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		24. SCALE: None			
LOCATION SKETCH/COMMENTS and soil plug 2/27/14 COC #: L802282014-01H					

Recorded By

J. Neutzel

Date 3/4/14

QA By

T. [Signature]

Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 204 FPS
SVP 164229

14

PROJECT Coldwater Creek

INSPECTOR: G. Neutzel

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silty Clay, brown, little v. fine sand, low plasticity, moist - CL	55/39	5477	6012	SVP164229	1408	yellow brown w/te glaucous
	0.5		58/6119			SVP164230	1412	
	1		52/5622				1415	
	1.5	Silt, brown little clay, little to some v. fine sand, low p	39/5477			Archive	1407	
	2	Borehole terminated						Soil
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By

J. Neutzel

Date 2/27/14

QA By

T. [Signature]

Date 3-7-14

15

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 164231	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 205 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Chuck Finkenberg / Adam Queen		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 865164 N1075086			
Meter - Background 44-9 E - 34 cpm 44-10 C - 5206 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
21. TOTAL CORE RECOVERY N/A		RAD SAMPLES 4		QA/QC SAMPLES 1 set of 2	
23. SIGNATURE OF INSPECTOR Gary Neutzel		ARCHIVE SAMPLE 0		OTHER (SPECIFY) N/A	
LOCATION SKETCH/COMMENTS COC #: LE02282014-01H SCALE: None					

Recorded By G. Neutzel Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 205 FPS
SVP 164231

PROJECT: Coldwater Creek

INSPECTOR: G. Neutzel

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey silt, brown, little clay to little v. fine sand, low plasticity, moist (FILL)	52			SVP 164231 1421		Collect QC/QA Soil sampler SVP 164231-1 SVP 164231-2 Extra 7 of 13 QC/QA
	0.5		6214			ISO Th gamma spec		
	1		50			1424		
	1.5		6112					
	2		37			1427		
	2.5		5865					
	3	up piece of concrete with 1 1/2 to 2 ft interval	49			SVP 164232 1430		
	3.5		6019			ISO Th gamma spec		
	4		55			1434		silt, little clay little to small
	4.5		6196					
	5		60			SVP 164233 1437		
	5.5		5953			ISO Th gamma spec		
	6	Clayey silt, med. brown, little v. fine sand, low plasticity, moist	49			1439		transition
	6.5	Silty CLAY, medium brown, little v. fine sand, medium plastic, moist - CL	60			1441		si CL
	7		5588					
	7.5		37			1457		
	8		6476					
	8.5		55			1459		more clayey but not CH
	9		6082					
	9.5		56			1501		
	10		5932					
	10.5		65			SVP 164234 1453		
	11		5680			ISO Th gamma spec		
	11.5	Borehole terminated						soil
	12							
	12.5							
	13							
	13.5							
	14							
	14.5							
	15							
	15.5							
	16							
	16.5							
	17							
	17.5							
	18							
	18.5							
	19							
	19.5							
	20							

Recorded By G. Neutzel Date 2/27/14 QA By [Signature] Date 3-7-14

17

HTRW DRILLING LOG				DISTRICT: St. Louis USACE		HOLE NUMBER SVP	
1. COMPANY NAME: Leidos				2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek				4. LOCATION: # 206 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Chuck Finkenbein / Adam Queen				6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865048 N1075886			
Meter - Background				9. SURFACE ELEVATION: N/A			
44-9 E - 34 cpm				10. DATE STARTED: 2/27/14		11. DATE COMPLETED: 2/27/14	
44-10 C - 5206 cpm							
12. OVERBURDEN THICKNESS: N/A				15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A				16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs				17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED		19. TOTAL NUMBER OF CORE BOXES: N/A	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS		RAD SAMPLES	
N/A		N/A		N/A		2	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING		OTHER (SPECIFY)	
Backfill using bentonite		w/bentonite		N/A		N/A	
23. SIGNATURE OF INSPECTOR G. Neutzling							
LOCATION SKETCH/COMMENTS COC #: LE02282014-01H							

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 206 FPS
SVP 164235

18

PROJECT: Coldwater Creek			INSPECTOR: G. Neutzling			SHEET 2 of 2		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, medium brown, some little clay, little v. fine sand, low plasticity - ML	59/5970	-	-	SVP164235 1508 Iso Th gamma spec	-	piece of plastic v. silty
	0.5		47/6430	-	-	1511	-	
	1.5	Clayey SILT, medium brown, little v. fine sand, low plasticity, moist - ML	50/5697	-	-	SVP164236 1514 Iso Th gamma spec	-	more clayey Archive Submitted 2/27/14 SVP167075 2/27/14
	2	Borehole terminated						(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 2/27/14 QA By [Signature] Date 3-7-14

19

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP 164217	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek			4. LOCATION: # 198 FPS (Flood Plain Systematic)		
5. NAME OF DRILLER: <i>Chuck Finkenbain / Adam Queen</i>			6. MANUFACTURERS DESIGNATION OF DRILL: N/A		
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES <i>QB 12-15-14</i> <i>E 8651069 N10757855</i>	
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 <i>E - 34 cpm</i>		10. DATE STARTED: <i>2/27/14</i>			
44-10 <i>C - 5206 cpm</i>		11. DATE COMPLETED <i>2/27/14</i>			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE <i>2.0 ft bgs</i>		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES: N/A					
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
21. TOTAL CORE RECOVERY: N/A		RAD SAMPLES		QA/QC SAMPLES	
		2		1	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		SCALE: None			
LOCATION SKETCH/COMMENTS <i>COC # LE02282014 - DFT 01H 3/4/14</i>					

Recorded By *J. Neutzling* Date *3/4/14* QA By *T. [Signature]* Date *3-7-14*

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER *198 FPS*
SVP 164217

20

PROJECT: Coldwater Creek		INSPECTOR: <i>G. Neutzling</i>					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sand, low plasticity, moist (FILL)	<i>64</i>			<i>SVP164217</i>		
	0.5		<i>6199</i>			<i>1525</i>		
	1		<i>59</i>			<i>1527</i>		
	1.5	Clayey SILT, medium brown, little v. fine sand, trace gravel, low plasticity, moist (FILL) - ML	<i>62</i>			<i>SVP164218</i>		<i>trgr</i>
	2		<i>5891</i>			<i>1529</i>		
	3		<i>47</i>			<i>1523</i>		<i>trgr</i>
	4	Borehole terminated.	<i>5416</i>			<i>1523</i>		
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By *J. Neutzling* Date *2/27/14* QA By *T. [Signature]* Date *3-7-14*

21

HTRW DRILLING LOG

DISTRICT: St. Louis USACE

HOLE NUMBER

SVP 1642311

1. COMPANY NAME: Leidos

2. DRILL SUBCONTRACTOR: Leidos

SHEET 1 OF 2

3. PROJECT: Coldwater Creek

4. LOCATION: #207 FPS (Flood Plain Systematic)

5. NAME OF DRILLER: Chuck Pinkerton/Adam Queen

6. MANUFACTURERS DESIGNATION OF DRILL: N/A

7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT

Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve

8. HOLE COORDINATES

E 865048 N 1075684

Meter - Background

44-9 E - 34 cpm

44-10 C - 5206 cpm

9. SURFACE ELEVATION: N/A

12. OVERBURDEN THICKNESS: N/A

15. DEPTH GROUNDWATER ENCOUNTERED: N/A

13. DEPTH DRILLED INTO ROCK: N/A

16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A

14. TOTAL DEPTH OF HOLE: 2.5 ft bgs

17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A

18. GEOTECHNICAL SAMPLES: N/A

DISTURBED

UNDISTURBED

19. TOTAL NUMBER OF CORE BOXES: N/A

20. SAMPLES FOR CHEMICAL ANALYSIS

VOC

METALS

RAD SAMPLES

QA/QC SAMPLES

ARCHIVE SAMPLE

21. TOTAL CORE RECOVERY: N/A

N/A

N/A

N/A

2

0

1

22. DISPOSITION OF HOLE

BACKFILLED

MONITORING

OTHER (SPECIFY)

23. SIGNATURE OF INSPECTOR

Backfill using bentonite

w/bentonite


N/A

N/A

LOCATION SKETCH/COMMENTS

COC #: LE02282014-01H

SCALE: None



Recorded By

J. Neutzhung

Date 3/4/14

QA By

T. [Signature]

Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER

SVP 1642311

PROJECT: Coldwater Creek

INSPECTOR:

G. Neutzhung

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0		Silty CLAY, med brown, gray mottled, trace sand, trace carbonate low plasticity, moist - CL (Fill)	52			SVP164211		
0.5		Clayey SILT, brown, little v. fine sandy low plasticity, moist - ML	6140			1583		
1		wt trace gravel (Fill)	50			1537		
1.5			5987					
2			53			1534		
2.5			5874					
3								
3.5		Silty CLAY, brown, little v. fine sandy low plasticity, moist - CL	76			SVP164212		
4			5446			1531		
4.5						1507th gamma spec		
5			54			1550		
5.5			5829			1507th gamma spec		
6		Probe terminated						
7								
8								
9								
10								

Recorded By

J. Neutzhung

Date 2/27/14

QA By

T. [Signature]

Date 3-7-14

23

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP164203	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 192 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Chuck Krakenborn / Adam Queen		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES QB 12-15-14 E 864990, N 10755830			
Meter - Background 44-9 E - 34 cpm 44-10 C - 5206 cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 2.5 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES N/A		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		21. TOTAL CORE RECOVERY N/A			
22. DISPOSITION OF HOLE Backfill using bentonite		23. SIGNATURE OF INSPECTOR G. Neutzling			
LOCATION SKETCH/COMMENTS COC #: LE02282014-01H SCALE: None					

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 192 FPS
SVP164203

24

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0	35	SILT, dark brown, little clay Some v. fine sand, trace gravel, low plasticity, moist - ML (FILL)	6019	-	-	SVP164203 1561 IsoTh gamma spec	-	Collect QC/QA Soil samples SVP164203-1 SVP164203-2
0.5	55	Silty CLAY, brown, little v. fine sand, low plasticity, moist - CL	5993	-	-	SVP164204 1553 IsoTh gamma spec	-	si CL
1	52	becomes medium brown (FILL)	5040	-	-	1565	-	med br si CL
1.5	52	Clayey SILT, brown, little v. fine sand, trace gravel, low plasticity, moist - ML (FILL)	5836	-	-	1558	-	cl si trgr FILL
2	65	SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML	5912	-	-	Archive 1601	-	si little cl
2.5		Borehole terminated						
6								
7								
8								
9								
10								

Recorded By G. Neutzling Date 2/27/14 QA By [Signature] Date 3-7-14

25

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 164219	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 199 FPS (Flood Plain systematic auger)			
5. NAME OF DRILLER: Juan Alvarado/Antonio Montenegro		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: 88 0812-15-14 E 864990 N10757853			
Meter - Background 44-9 F - 42 cpm 44-10 C - 7586 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS: N/A		10. DATE STARTED: 3/4/14 11. DATE COMPLETED: 3/4/14			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		21. TOTAL CORE RECOVERY: N/A			
22. DISPOSITION OF HOLE Backfill using bentonite		23. SIGNATURE OF INSPECTOR: Gary Neutzling			
LOCATION SKETCH/COMMENTS COC # LF03042014-01H					

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 199 FPS
SVP 164219

26

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0	57/7316	Silty CLAY, brown, trace sand, low plasticity, moist (FILL)	53/7345	-	-	SVP 164219-0922	-	Collect QC/QA soil samples SVP 164219-1 SVP 164219-2
1	56/7112	Silty CLAY, brown, trace sand, low plasticity, little crushed limestone trace asphalt pieces, moist - CL (FILL)	46/7444	-	-	SVP 164219-0937	-	moved ~1 1/2 ft to East
2		Borehole terminated (auger refusal)				Archived 0939	-	
3								
4								
5								
6								
7								
8								
9								
10								

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

27

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162338	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 1120 (systematic array)			
5. NAME OF DRILLER: Juan Alvarez, Antonio Martinez, Chumbe F		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES Q812-15-14 E 8649638 N 107576157			
Meter - Background 44-9 F - 42 cpm 44-10 C - 7586 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		21. TOTAL CORE RECOVERY: N/A			
22. DISPOSITION OF HOLE Backfill using bentonite		23. SIGNATURE OF INSPECTOR Gary Neutzling			
LOCATION SKETCH/COMMENTS COC #: LE03042014-01H SCALE: None					

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1120
SVP 162338

28


PROJECT: Coldwater Creek		INSPECTOR: G Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, some clay trace sand, trace roots, brown plastic, moist - ML (FILL)	60 / 7579	-	-	SVP 162338 1000 Iso Th gamma spec	-	
	0.5		67 / 7520	-	-	1005	-	
	1.0	Silty CLAY, brown, trace sand, low plasticity, moist - CL (FILL)	41 / 7523	-	-	1007	-	
	1.5	w/ trace gravel below ~ 1 1/2 ft	67 / 7511	-	-	SVP 162339 1010 Iso Th gamma spec	-	
	2.0	Borehole terminated						
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

29

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162362	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1132 (systematic array)			
5. NAME OF DRILLER: Juan Alvarado/Chuck Finkenbaur		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864963 N1075885			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 F - 42 cpm		10. DATE STARTED: 3/4/14		11. DATE COMPLETED 3/4/14	
44-10 C - 7586 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC	METALS	RAD SAMPLES	QA/QC SAMPLES
N/A		N/A	N/A	2	0
22. DISPOSITION OF HOLE		BACKFILLED	MONITORING	OTHER (SPECIFY)	23. SIGNATURE OF INSPECTOR
Backfill using bentonite		w/bentonite	N/A	N/A	G. Neutzling

LOCATION SKETCH/COMMENTS
COC #: LE03042014-01H



Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1132
SVP 162362

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
	0	Clayey SILT, brown, little to some v. fine sandy, low plasticity, moist - ML	57/8117	-	-
	0.5		59/7730	-	-
	1		64/7702	-	-
	1.5		73/7497	-	-
	2.0	Borehole terminated			
	5				
	6				
	7				
	8				
	9				
	10				

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

31

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP162350	
1 COMPANY NAME: Leidos		2 DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3 PROJECT: Coldwater Creek		4 LOCATION: # 1126 (Biased TD/Systematic auger)			
5 NAME OF DRILLER: Juan Alvarado/Chuck Finkbein		6 MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES: E 864963 N1075885 moved to actual ditch New Coord. E 864979 N1075909			
Meter - Background 44-9 F - 42 cpm 44-10 C - 7586 cpm		9 SURFACE ELEVATION: N/A			
12 OVERBURDEN THICKNESS: N/A		15 DEPTH GROUNDWATER ENCOUNTERED: N/A			
13 DEPTH DRILLED INTO ROCK: N/A		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		19 TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		21 TOTAL CORE RECOVERY: N/A			
22. DISPOSITION OF HOLE		23. SIGNATURE OF INSPECTOR			
Backfill using bentonite		SCALE: None			
LOCATION SKETCH/COMMENTS COC #: LE03042014-01H					

Recorded By

J. Neutzling

Date 3/4/14

QA By

T. [Signature]

Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1126
SVP162350

32

PROJECT: Coldwater Creek		INSPECTOR: G. Neut		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	1	Clayey SILT, brown, little v. fine sand, low plasticity, moist - ML	64/7292	-	-	SVP162350 1102 IsoTh gamma spec	-	moved from pinned loc to actual drainage ditch
	2		70/7524	-	-	SVP162351 1104 IsoTh gamma spec	-	Collect QC/QA soil samples SVP162350-1 SVP162350-2
	3		64/7853	-	-	1106	-	
	4		59/8053	-	-	Archive 1108 IsoTh gamma spec	-	SVP164550 submitted archive via 6/12/14 per 11/20/15
	5	Borehole terminated						
	6							
	7							
	8							
	9							
	10							

Recorded By

J. Neutzling

Date 3/4/14

QA By

T. [Signature]

Date 3-7-14

33

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP167068	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # former 1126 (systematic auger)			
5. NAME OF DRILLER: Juan Alvarado/Charles Fikensbein/Anthony Hartung		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864963 N 1075885			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/4/14			
11. DATE COMPLETED: 3/4/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR: Gary Neutzling		24. SCALE: None			
LOCATION SKETCH/COMMENTS CAC #: L203052014-01H					

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER former 1126
SVP167068

PROJECT: Coldwater Creek

INSPECTOR: G. Neutzling

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, some v. fine sand, little clay, low plasticity, moist - ML	55/8268	—	—	SVP167068 1319 Iso Th gamma spec	—	
	0.5		55/7893	—	—	1323	—	
	1		61/8113	—	—	1326	—	
	1.5		62/8082	—	—	SVP167069 1320 Iso Th gamma spec	—	
	2	Borehole terminated						
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/4/14 QA By [Signature] Date 3-7-14

39

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 164081	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 133 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES Q8 12-15-14 E 865280 N 1073863			
9. SURFACE ELEVATION N/A		10. DATE STARTED: 3/5/14			
11. DATE COMPLETED: 3/5/14					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES N/A					
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
21. TOTAL CORE RECOVERY N/A		RAD SAMPLES		QA/QC SAMPLES	
N/A		2		1 set of 2	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		OTHER (SPECIFY)		N/A	
LOCATION SKETCH/COMMENTS COC #: LE03052014-02H		SCALE: None			

Recorded By J. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 133 FPS
SVP 164081

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey Silt, med brown, little v. fine sand, low plasticity, moist - ML	65 / 8314	-	-	SVP164081 0815	-	Collected QC/QA Soil samples SVP164081-1 SVP164081-2 Extra 8 of 13
	0.5		57 / 8173	-	-	0817	-	CLSI 3/5/14
	1.5	Silty CLAY, medium brown, trace v. fine sand, low plasticity, moist - CL	58 / 8132	-	-	0818	-	SiCL
	2		65 / 8214	-	-	SVP164082 0813	-	Soil
	2	Borehole terminated						
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By J. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

41

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 164087	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 136 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Juan Alvarado/Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865338 N1073967			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 E - 53 cpm		10. DATE STARTED: 3/5/14		11. DATE COMPLETED: 3/5/14	
44-10 K - 8281 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		21. TOTAL CORE RECOVERY N/A			
N/A		N/A			
22. DISPOSITION OF HOLE		23. SIGNATURE OF INSPECTOR			
Backfill using bentonite		w/bentonite			
LOCATION SKETCH/COMMENTS CUC #: LE03052014-02H		SCALE: None			

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 136 FPS
SVP 164087

42

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, medium brown, little v. fine sand, low plasticity, moist - ML	53/8374	-	-	SVP164087 0837	-	
	1		50/8241	-	-	0838	-	
	1		43/8396	-	-	0839	-	
	2.0		65/8651	-	-	SVP164088 0840	-	
	2.0	Silty CLAY, dark brown, trace v. fine sand, low plasticity, moist - CL	71/8500	-	-	SVP164089 0841	-	
	3		59/8452	-	-	0849	-	
	3	CLAY, mix of dark brown & brown, some silt, trace sand, high plasticity, moist - CH	53/8258	-	-	0851	-	FAT CLAY LL > 50
	4		56/8147	-	-	0853	-	
	4		59/8403	-	-	0855	-	
	5		51/8191	-	-	0857	-	
	5		73/8170	-	-	SVP164090 0900	-	
	6.0		60/8419	-	-	Archive 0904	-	
	6.0	Borehole terminated				ISO 78 gamma spec		Soil
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

43

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP164095	
1 COMPANY NAME: Leidos		2 DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3 PROJECT: Coldwater Creek		4 LOCATION # 139 FPS (Flood Plain Systematic)			
5 NAME OF DRILLER: Juan Alvarez/Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL: N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		8 HOLE COORDINATES			
Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		E 865396 N 1074068			
9 SURFACE ELEVATION N/A		10 DATE STARTED 3/5/14			
11 DATE COMPLETED 3/5/14		12 OVERBURDEN THICKNESS N/A			
13 DEPTH DRILLED INTO ROCK: N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A		18 GEOTECHNICAL SAMPLES: N/A			
DISTURBED		UNDISTURBED		19 TOTAL NUMBER OF CORE BOXES: N/A	
20 SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
22 DISPOSITION OF HOLE		BACKFILLED		MONITORING WELL	
Backfill using bentonite		w/bentonite		N/A	
23 SIGNATURE OF INSPECTOR		24 SCALE: None		25	
LOCATION SKETCH/COMMENTS					
COC #: L&D3052014-02H					

Recorded By

J. Neutzing

Date

3/5/14

QA By

T. [Signature]

Date

3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 139 FPS
SVP164095

44

PROJECT: Coldwater Creek

INSPECTOR

G. Neutzing

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0	0	Silty CLAY, brown, trace sand, low plasticity, moderate plasticity, moist - CL	43/8333	-	-	SVP164095 0938 Iso Th gamma spec	-	Collect QC/QA Possible Fill soil sampler Same SVP164095-1 SVP164095-2
0.5	0.5		60/8301	-	-	0931	-	
1	1		53/8528	-	-	0936	-	
1.5	1.5		61/8143	-	-	SVP164096 0934 Iso Th gamma spec	-	
2.0	2.0	Borehole terminated.						(S&I)
5	5							
6	6							
7	7							
8	8							
9	9							
10	10							

Recorded By

J. Neutzing

Date

3/5/14


QA By

T. [Signature]

Date

3-7-14

45

HTRW DRILLING LOG		DISTRICT: St. Louis USACE	HOLE NUMBER SVP 164097
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos	
3. PROJECT: Coldwater Creek		4. LOCATION: # 147 FPS (Flood Plain Systematic)	
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 865520 N 1074162 3/5/14	
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/5/14	
11. DATE COMPLETED: 3/5/14		12. OVERBURDEN THICKNESS: N/A	
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A	
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A	
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS: VOC, METALS, RAD SAMPLES, QA/QC SAMPLES, ARCHIVE SAMPLE	
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE: BACKFILLED, MONITORING, OTHER (SPECIFY)	
23. SIGNATURE OF INSPECTOR: Gary Neutzling		24. SCALE: None	
LOCATION SKETCH/COMMENTS: COC # LE03052014-02H			
			

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 147 FPS 3/5/14 46
SVP 164097

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, brown, little v. fine sand, low plasticity, moist - rxl	40/8309			SVP 164097 0958 Iso Th gamma spec		top 3" frozen as all are today
	0.5		71/8540			SVP 164098 1000 Iso Th gamma spec		
	1		68/8294			Archival 1002 Iso Th gamma spec		
	1.5		57/8284			Archival 0957 Iso Th gamma spec		
	2.0	Borehole terminated						(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

47

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164091	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 137 FPS (Blood Plains Systematic)			
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		8. HOLE COORDINATES Q 8 12-15-14 E 8652274 N107396757			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 E - 39 cpm		10. DATE STARTED: 3/5/14			
44-10 K - 8316 cpm		11. DATE COMPLETED 3/5/14			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		RAD SAMPLES	
N/A		N/A		2	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		21. TOTAL CORE RECOVERY: N/A		24. SIGNATURE OF INSPECTOR	
LOCATION SKETCH/COMMENTS		SCALE: None		25. SIGNATURE OF INSPECTOR	
COC #: LE03052014-02H				26. SIGNATURE OF INSPECTOR	
Approximately				27. SIGNATURE OF INSPECTOR	
				28. SIGNATURE OF INSPECTOR	
				29. SIGNATURE OF INSPECTOR	
				30. SIGNATURE OF INSPECTOR	
				31. SIGNATURE OF INSPECTOR	
				32. SIGNATURE OF INSPECTOR	
				33. SIGNATURE OF INSPECTOR	
				34. SIGNATURE OF INSPECTOR	
				35. SIGNATURE OF INSPECTOR	
				36. SIGNATURE OF INSPECTOR	
				37. SIGNATURE OF INSPECTOR	
				38. SIGNATURE OF INSPECTOR	
				39. SIGNATURE OF INSPECTOR	
				40. SIGNATURE OF INSPECTOR	
				41. SIGNATURE OF INSPECTOR	
				42. SIGNATURE OF INSPECTOR	
				43. SIGNATURE OF INSPECTOR	
				44. SIGNATURE OF INSPECTOR	
				45. SIGNATURE OF INSPECTOR	
				46. SIGNATURE OF INSPECTOR	
				47. SIGNATURE OF INSPECTOR	
				48. SIGNATURE OF INSPECTOR	
				49. SIGNATURE OF INSPECTOR	
				50. SIGNATURE OF INSPECTOR	
				51. SIGNATURE OF INSPECTOR	
				52. SIGNATURE OF INSPECTOR	
				53. SIGNATURE OF INSPECTOR	
				54. SIGNATURE OF INSPECTOR	
				55. SIGNATURE OF INSPECTOR	
				56. SIGNATURE OF INSPECTOR	
				57. SIGNATURE OF INSPECTOR	
				58. SIGNATURE OF INSPECTOR	
				59. SIGNATURE OF INSPECTOR	
				60. SIGNATURE OF INSPECTOR	
				61. SIGNATURE OF INSPECTOR	
				62. SIGNATURE OF INSPECTOR	
				63. SIGNATURE OF INSPECTOR	
				64. SIGNATURE OF INSPECTOR	
				65. SIGNATURE OF INSPECTOR	
				66. SIGNATURE OF INSPECTOR	
				67. SIGNATURE OF INSPECTOR	
				68. SIGNATURE OF INSPECTOR	
				69. SIGNATURE OF INSPECTOR	
				70. SIGNATURE OF INSPECTOR	
				71. SIGNATURE OF INSPECTOR	
				72. SIGNATURE OF INSPECTOR	
				73. SIGNATURE OF INSPECTOR	
				74. SIGNATURE OF INSPECTOR	
				75. SIGNATURE OF INSPECTOR	
				76. SIGNATURE OF INSPECTOR	
				77. SIGNATURE OF INSPECTOR	
				78. SIGNATURE OF INSPECTOR	
				79. SIGNATURE OF INSPECTOR	
				80. SIGNATURE OF INSPECTOR	
				81. SIGNATURE OF INSPECTOR	
				82. SIGNATURE OF INSPECTOR	
				83. SIGNATURE OF INSPECTOR	
				84. SIGNATURE OF INSPECTOR	
				85. SIGNATURE OF INSPECTOR	
				86. SIGNATURE OF INSPECTOR	
				87. SIGNATURE OF INSPECTOR	
				88. SIGNATURE OF INSPECTOR	
				89. SIGNATURE OF INSPECTOR	
				90. SIGNATURE OF INSPECTOR	
				91. SIGNATURE OF INSPECTOR	
				92. SIGNATURE OF INSPECTOR	
				93. SIGNATURE OF INSPECTOR	
				94. SIGNATURE OF INSPECTOR	
				95. SIGNATURE OF INSPECTOR	
				96. SIGNATURE OF INSPECTOR	
				97. SIGNATURE OF INSPECTOR	
				98. SIGNATURE OF INSPECTOR	
				99. SIGNATURE OF INSPECTOR	
				100. SIGNATURE OF INSPECTOR	

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 137 FPS
SVP 164091

48


PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, brown, little v. fine sand, low plasticity, moist - ML	49/8395	-	-	SVP164091 1015 Iso Th gamma spec	-	Same
	0.5		44/8374	-	-	1016	-	
	1		53/8188	-	-	SVP164092 1017 Iso Th gamma spec	-	
	1.5		46/8314	-	-	Archive 1013 Iso Th gamma spec	-	
	2.0	Borehole terminated						(Soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

49

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVPI63695	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 41 FP (Biased Flood Plains)			
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865228 N1074141			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 E - 39 cpm		10. DATE STARTED: 3/5/14		11. DATE COMPLETED 3/5/14	
44-10 K - 8310 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
21. TOTAL CORE RECOVERY: N/A		RAD SAMPLES		QA/QC SAMPLES	
		2		0	
23. SIGNATURE OF INSPECTOR		ARCHIVE SAMPLE		2	
G. Neutzling		N/A		N/A	

LOCATION SKETCH/COMMENTS
COC #: L603052014-02H



Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 41FP
SVP163695

50

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0		Silty CLAY, brown, little v. fine sand, low plasticity, moist - ML-CL	55/8298	-	-	SVP163695 1029 Iso Th gamma spec	-	Seamed clayey.
0.5		SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML	47/8537	-	-	1031	-	
1		Clayey SILT, brown, trace v. fine sand, low plasticity, moist - ML	55/8018	-	-	1035	-	
1.5			65/8383	-	-	SVP163696 1026 Iso Th gamma spec	-	
2.0		Borehole terminated						(soil)
5								
6								
7								
8								
9								
10								

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

51

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164103	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 142 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez / Chuck		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 865338 N 1074169			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/5/14			
11. DATE COMPLETED: 3/5/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		14. TOTAL DEPTH OF HOLE: 2.0 ft bgs			
15. DEPTH GROUNDWATER ENCOUNTERED: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS: N/A			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE: Backfilled using bentonite			
23. SIGNATURE OF INSPECTOR: Gary Neutzling		SCALE: None			
LOCATION SKETCH/COMMENTS: COC #: LE03062014-01H					

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14


52

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER 142 FPS SVP164103		SHEET 2 of 2	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		REMARKS	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
0		SILT, brown, little clay, little v. fine sandy lens, plasticity, moist - ML	54/8479	-	-
0.5			68/8170	-	-
1			52/8023	-	-
1.5		SILT, med brown, little clay, trace v. fine sandy lens, plasticity, moist - ML	67/7975	-	-
2		Borehole terminated			
5					
6					
7					
8					
9					
10					

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

63

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164105	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION #143FPS (Flood Plain Systematic)			
5. NAME OF DRILLER Juan Alvarado/Antonia Martinez/Chuck Pinkerton		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES Q8 1215.14 E 865222 N107416957			
9. SURFACE ELEVATION N/A		10. DATE STARTED 3/5/14			
11. DATE COMPLETED 3/5/14		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
15. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
17. GEOTECHNICAL SAMPLES N/A		18. TOTAL NUMBER OF CORE BOXES: N/A			
19. SAMPLES FOR CHEMICAL ANALYSIS N/A		20. TOTAL CORE RECOVERY N/A			
21. DISPOSITION OF HOLE Backfill using bentonite		22. SIGNATURE OF INSPECTOR G. Neutzhung			
23. LOCATION SKETCH/COMMENTS COC #: LE09062014-01H		24. SCALE: None			



Recorded By G. Neutzhung Date 3/5/14 QA By [Signature] Date 3-7-14

54

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER SVP164105		SHEET 2 of 2	
PROJECT Coldwater Creek		INSPECTOR: G. Neutzhung		449 NAI	
USCS		Depth (ft bgs)		Description of Materials	
0		57		SILT, brown, little to some clay, little v. fine sand, low plasticity, moist - ML	
0.5		53		8267	
1		64		8239	
1.5		60		8081	
2.0		Borehole terminated			
5					
6					
7					
8					
9					
10					

Remarks: Collect QC/QA soil samples SVP164105-1 SVP164105-2

Remarks: more clayey but still ML

Remarks: (soil)

Recorded By G. Neutzhung Date 3/5/14 QA By [Signature] Date 3-7-14

55

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP164109	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 146 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Juan Alvarado / Antonio Martinez / Chuck E. Baker		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES 28 08 12.15-14 E 865280 N 1074270 61			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/5/14			
11. DATE COMPLETED: 3/5/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
15. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
17. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
18. SAMPLES FOR CHEMICAL ANALYSIS: N/A		VOC		METALS	
19. RAD SAMPLES: 2		QA/QC SAMPLES: 0		ARCHIVE SAMPLE: 1	
20. DISPOSITION OF HOLE: BACKFILLED		MONITORING		OTHER (SPECIFY)	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR: <i>G. Neutzling</i>					
LOCATION SKETCH/COMMENTS COC #: LE03062014-01H SCALE: None					

Recorded By *G. Neutzling* Date *3/5/14* QA By *[Signature]* Date *3-7-14*

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 146 FPS
SVP 164109

PROJECT: Coldwater Creek		INSPECTOR: <i>G. Neutzling</i>					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sand, low plasticity, moist-ML	49/8151	-	-	SVP164109 1337 Iso Th gamma Spec	-	
	0.5		54/8129	-	-	1341	-	
	1		63/7845	-	-	SVP164110 1342 Iso Th gamma Spec	-	
	1.5		46/8057	-	-	Archive 1345 Iso Th gamma Spec	-	
	2	Borehole terminated						(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By *G. Neutzling* Date *3/5/14* QA By *[Signature]* Date *3-7-14*

57

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP164111	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 147 FPS (Flood Plain Systematic)			
5. NAME OF DRILLER: Juan Alvarado/Antonio Martinez/Chade Finkbeiner		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES QS 12-15-14 E 8651646 N 1074270			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/5/14			
11. DATE COMPLETED: 3/5/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
15. TOTAL DEPTH OF HOLE: 6.0 ft bgs		16. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
17. GEOTECHNICAL SAMPLES: N/A		18. TOTAL NUMBER OF CORE BOXES: N/A			
19. SAMPLES FOR CHEMICAL ANALYSIS: N/A		20. TOTAL CORE RECOVERY: N/A			
21. DISPOSITION OF HOLE: Backfill using bentonite		22. SIGNATURE OF INSPECTOR: Gary Neutzling			
23. LOCATION SKETCH/COMMENTS COC #: LE 03062014-01H		24. SCALE: None			

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)


HOLE NUMBER 147 FPS
SVP164111

58

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	1	SILT, brown, little v. fine sand, little clay, low plasticity, moist - ML	61/8121	-	-	SVP164111 1347 350 Th gamma spec	-	Silt
	1.5		65/8176	-	-	SVP164112 1351 350 Th gamma spec	-	
	2.0		61/8038	-	-	1354	-	
	2.5	Clayey SILT, dark brown, trace sand, moderately plastic, moist - CL	59/8049	-	-	1357	-	more clayey
	3	CLAY dark brown, some silt, trace sand, tending to highly plastic, moist - CH	67/8024	-	-	SVP164113 1400 350 Th gamma spec	-	FAT clay
	3.5		58/8333	-	-	1403	-	
	4		48/8100	-	-	1408	-	
	4.5		50/8269	-	-	1409	-	
	5		52/8462	-	-	1416	-	
	5.5		43/8227	-	-	1418	-	
	6.0	Borehole terminated	57/8278	-	-	SVP164114 1420 350 Th gamma spec 3/5/14	-	
	6.5		58/8171	-	-	SVP164114 1420 350 Th gamma spec	-	(soil)
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

59

HTRW DRILLING LOG		DISTRICT St. Louis USACE	HOLE NUMBER SVP164117
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos	
3. PROJECT: Coldwater Creek		4. LOCATION #150 FFS	
5. NAME OF DRILLER: Juan Alvarez / Antonio Martinez / Choke		6. MANUFACTURERS DESIGNATION OF DRILL: N/A	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES QB 12-15-14 E 865243 N107437+59	
9. SURFACE ELEVATION N/A		10. DATE STARTED: 3/5/14	
11. DATE COMPLETED: 3/5/14		12. OVERBURDEN THICKNESS N/A	
13. DEPTH DRILLED INTO ROCK: N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A	
15. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A	
17. GEOTECHNICAL SAMPLES: N/A		18. TOTAL NUMBER OF CORE BOXES: N/A	
19. SAMPLES FOR CHEMICAL ANALYSIS VOC METALS RAD SAMPLES QA/QC SAMPLES ARCHIVE SAMPLE N/A N/A N/A 2 1 set of 2 0		20. TOTAL CORE RECOVERY: N/A	
21. DISPOSITION OF HOLE Backfill using bentonite w/bentonite N/A N/A		22. SIGNATURE OF INSPECTOR G. Neutzling	
LOCATION SKETCH/COMMENTS COC #: LE03062014-01H SCALE: None			
			

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 150 FFS
SVP164117

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sandy, low plasticity, moist - ML	78/8151	-	-	SVP164117 1423 Iso Th gamma spec	-	Collect QG/QA Soil Samples SVP164117-1 SVP164117-2 Extra 90 LBS
	1/0.5		57/8123	-	-	1427	-	Same
	2/1		54/8230	-	-	1429	-	
	3/1.5		57/8197	-	-	SVP164118 1434 Iso Th gamma spec	-	
	4/2.0	Borehole terminated						Soil
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/5/14 QA By [Signature] Date 3-7-14

HTRW DRILLING LOG

DISTRICT **St. Louis USACE** HOLE NUMBER **SVP K4121**

1 COMPANY NAME **Leidos** 2 DRILL SUBCONTRACTOR: **Leidos** SHEET 1 OF 2

3 PROJECT **Coldwater Creek** 4 LOCATION **# 153 FPS (Flood Plain Systematic)**

5 NAME OF DRILLER **Juan Alvarez / Antonio Martinez / [Signature]** 6 MANUFACTURERS DESIGNATION OF DRILL: **N/A**

7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT **Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve** 8 HOLE COORDINATES **E 865164 N1074472**

9 SURFACE ELEVATION **N/A**

10 DATE STARTED: **3/5/14** 11 DATE COMPLETED **3/5/14**

12 OVERBURDEN THICKNESS **N/A** 15 DEPTH GROUNDWATER ENCOUNTERED **N/A**

13 DEPTH DRILLED INTO ROCK: **N/A** 16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED **N/A**

14 TOTAL DEPTH OF HOLE **2.0 ft bgs** 17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY) **N/A**

18 GEOTECHNICAL SAMPLES **N/A** 19 TOTAL NUMBER OF CORE BOXES: **N/A**

20 SAMPLES FOR CHEMICAL ANALYSIS

VOC	METALS	RAD SAMPLES	QA/QC SAMPLES	ARCHIVE SAMPLE
N/A	N/A	2	1 set of 2	1

21 TOTAL CORE RECOVERY: **N/A**

22 DISPOSITION OF HOLE **Backfill using bentonite** 23 SIGNATURE OF INSPECTOR **[Signature]**

LOCATION SKETCH/COMMENTS **COC # : LE03062014-02H**

Approximately

Recorded By **G. Neutzling** Date **3/5/14** QA By **[Signature]** Date **3-7-14**

HTRW DRILLING LOG (Continuation Sheet)

PROJECT: **Coldwater Creek** INSPECTOR **G. Neutzling** SHEET 2 of 2

HOLE NUMBER **153 FPS** SVPI64121

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little v. fine sand, little clay, low plasticity, moist - ML	59/8201			SVP164121 1437 Iso Th gamma spec		Collect 60/90 soil sample for SVPI64121-1 SVPI64121-2
	0.5		59/8125			SVP164122 1442 Iso Th gamma spec		Same
	1		46/8176			1447		
	1.5		54/8310			Archive 1449 Iso Th gamma spec		
	2.0	Borehole terminated						soil
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By **G. Neutzling** Date **3/5/14** QA By **[Signature]** Date **3-7-14**

HTRW DRILLING LOG

DISTRICT: St. Louis USACE HOLE NUMBER: SVP 164123

1. COMPANY NAME: Leidos 2. DRILL SUBCONTRACTOR: Leidos SHEET 1 OF 2

3. PROJECT: Coldwater Creek 4. LOCATION: #154 FPS (Flood Plain Systematic)

5. NAME OF DRILLER: Chuck Finkenauer / Antonio Martinez / Juan 6. MANUFACTURERS DESIGNATION OF DRILL: N/A

7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve 8. HOLE COORDINATES: QB 12-15-14 E 865048 N 10744723

9. SURFACE ELEVATION: N/A

10. DATE STARTED: 3/5/14 11. DATE COMPLETED: 3/5/14

12. OVERBURDEN THICKNESS: N/A 15. DEPTH GROUNDWATER ENCOUNTERED: N/A

13. DEPTH DRILLED INTO ROCK: N/A 16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A

14. TOTAL DEPTH OF HOLE: 6.0 ft bgs 17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A

18. GEOTECHNICAL SAMPLES: N/A 19. TOTAL NUMBER OF CORE BOXES: N/A

20. SAMPLES FOR CHEMICAL ANALYSIS: VOC, METALS, RAD SAMPLES, QA/QC SAMPLES, ARCHIVE SAMPLE, 21. TOTAL CORE RECOVERY: N/A

22. DISPOSITION OF HOLE: BACKFILLED, MONITORING, OTHER (SPECIFY) 23. SIGNATURE OF INSPECTOR: Gary Neutzling

Backfill using bentonite w/bentonite N/A N/A

LOCATION SKETCH/COMMENTS: COC #: LF 03062014-02H

Approximately

Recorded By: G. Neutzling Date: 3/5/14 QA By: [Signature] Date: 3-7-14

HTRW DRILLING LOG (Continuation Sheet)

PROJECT: Coldwater Creek INSPECTOR: G. Neutzling SHEET 2 of 2

USCS Depth (ft bgs) Description of Materials 449 NAI PID Recovery Analytical Sample Blow Counts Remarks

1 5/1T brown, little clay, little v. fine sand, low plasticity, slightly moist to moist - n2 43/8561 - - SVP 164123 1512 1515 Collect QC/QA Soil sampler SVP 164123-1 SVP 164123-2

2 78/8451 - - SVP 164124 1522 1523 54/8626 - - 1523

3 65/8128 - - SVP 164125 1527 1532 57/8245 - - 1532

3.4 Silty CLAY, med brown, trace sand, moderate plasticity, moist - CL 58/8137 - - 1534

4.0 CLAY, dark brown, some silty, trace sand, high plasticity, moist - CH 63/8262 - - SVP 164126 1537 1537 Fat CLAY 58/8225 - - 1537

5 60/8173 - - 1540

6.0 48/8178 - - Archive 1329 1550th gamma spec

Borehole terminated

7 8 9 10

Ymm 3/5/14

Recorded By: G. Neutzling Date: 3/5/14 QA By: [Signature] Date: 3-7-14

71

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP167089	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: #176059 <i>3/19/14 (Horn bound EXP 164069) (128 FPS)</i>			
5. NAME OF DRILLER: David Guyan/Juan Alvarado/M. Sherman		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 864932 N 1073651			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/19/14			
11. DATE COMPLETED: 3/19/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 1.5 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS: VOC, METALS, RAD SAMPLES, QA/QC SAMPLES, ARCHIVE SAMPLE, 21. TOTAL CORE RECOVERY: N/A			
22. DISPOSITION OF HOLE: Backfill using bentonite		23. SIGNATURE OF INSPECTOR: <i>G. Neutzling</i>			
LOCATION SKETCH/COMMENTS: <i>and gross plug 3/19/14</i> COC #: LEO3202014-01H SCALE: None					

Recorded By *G. Neutzling* Date *3/19/14* QA By *Mandmeyer* Date *3/26/14*

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER
SVP167089

176059

3/19/14 72

PROJECT: Coldwater Creek

INSPECTOR: *G. Neutzling*

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey Silt, brown, little v. fine sandy, trace, low plasticity, moist - ML (possible fill)	62/6347	-	-	SVP167089 1355 IsoTh gamma spec	-	Collected QC/QA soil samples SVP167089-1 SVP167089-2
	0.5		62/6176	-	-	SVP167090 1400 IsoTh gamma spec	-	
	1	as pieces of yellowish brown silty CLAY w/in 1-1 1/2 ft interval	62/5956	-	-	Archiro 1403 IsoTh gamma spec	-	
	1.5	Borehole terminated						(soil)
	4							
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By *G. Neutzling* Date *3/19/14* QA By *Mandmeyer* Date *3/26/14*

73

HTRW DRILLING LOG		DISTRICT: St. Louis USACE	HOLE NUMBER SVP167091
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR: Leidos	
3. PROJECT Coldwater Creek		4. LOCATION #1760 (Horiz bound SVP164069)	
5. NAME OF DRILLER David J. [unclear] / Juan Alvarado / [unclear]		6. MANUFACTURERS DESIGNATION OF DRILL N/A (128FPS)	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864921 N1073651	
9. SURFACE ELEVATION N/A		10. DATE STARTED: 3/19/14	
11. DATE COMPLETED 3/19/14		12. OVERBURDEN THICKNESS N/A	
13. DEPTH DRILLED INTO ROCK N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A	
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A	
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS	
21. TOTAL CORE RECOVERY N/A		22. DISPOSITION OF HOLE	
23. SIGNATURE OF INSPECTOR		24. SIGNATURE OF DRILLER	
LOCATION SKETCH/COMMENTS COC #: LE03202014-01H and grass plug 3/19/14			
Approximately			

Recorded By J. Neutzling Date 3/19/14 QA By Mandel Myers Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER 1760	
PROJECT Coldwater Creek		INSPECTOR: G. Neutzling	
SHEET 2 of 2		SVP167091	
USCS	Depth (ft bgs)	Description of Materials	Remarks
	0.5	Clayey SILT, med brown, little v fine sandy low plasticity, moist - ML	SVP167091 1417 Iso Th gamma spec
	0.5		SVP167092 1419 Iso Th
	1.5		SVP167095 1421 Iso Th gamma spec
	1.5	Silty CLAY, dark brown, little sand, low plasticity, moist - CL	Archive 1440 Iso Th gamma spec
	2	Borehole terminated	soil

Recorded By J. Neutzling Date 3/19/14 QA By Mandel Myers Date 3/26/14


75

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 167093	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION #1761			
5. NAME OF DRILLER: David Gwynn / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864943 N 1073651			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 A - 36 cpm		10. DATE STARTED: 3/19/14		11. DATE COMPLETED 3/19/14	
44-10 K - 5798 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 1.5 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC	METALS	RAD SAMPLES	QA/QC SAMPLES
N/A		N/A	N/A	2	0
22. DISPOSITION OF HOLE		BACKFILLED	MONITORING W/ELL	OTHER (SPECIFY)	23. SIGNATURE OF INSPECTOR
Backfill using bentonite		w/bentonite	N/A	N/A	<i>G. Neutzling</i>

LOCATION SKETCH/COMMENTS

COC #: **LE03202014-01H**

SCALE: None



Recorded By

G. Neutzling

Date

3/19/14

QA By

Mandmeyer

Date

3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER **1761**
SVP **167093**

SHEET 2 of 2

PROJECT: **Coldwater Creek**

INSPECTOR:

G. Neutzling

USCS

Depth
(ft bgs)

Description of Materials

449

NAI

PID

Recovery

Analytical
SampleBlow
Counts

Remarks

0

*Silty Clay, brown, little
v fine sandy, low plasticity,
moist - CL*

72

-

-

SVP167093

1433

-

= 2X

*SiCl or CL 2X
could go
either way.*

1

5910

-

-

SVP167094

1433

-

2

58

-

-

SVP167094

1436

-

3

6024

-

-

SVP167094

1436

-

4

63

-

-

Archive

1438

-

5

6328

-

-

Iso Th

gamma

Spec

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

77

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP167096	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 1762 (Hony bound SVP164075 (22) (131FPS))			
5. NAME OF DRILLER: David Guyan/Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 864979 N 1073776			
Meter - Background		9. SURFACE ELEVATION: N/A			
44-9 A - 36 cpm		10. DATE STARTED: 3/19/14		11. DATE COMPLETED: 3/19/14	
44-10 K - 5798 cpm					
12. OVERBURDEN THICKNESS: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 3.5 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS: N/A		VOC: N/A		METALS: N/A	
		RAD SAMPLES: 7		QA/QC SAMPLES: 0	
		ARCHIVE SAMPLE: 0		21. TOTAL CORE RECOVERY: N/A	
22. DISPOSITION OF HOLE: Backfilled using bentonite		w/bentonite		23. SIGNATURE OF INSPECTOR: Gary Neutzling	
LOCATION SKETCH/COMMENTS: and grass plug 3/19/14 COC #: LE03202014-024 SCALE: None					

Recorded By G. Neutzling Date 3/19/14 QA By M. Adamez Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1762
SVP167096

78

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
	0	SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML	51/6000		SVP167096
	6.5		57/6122		SVP167097
	72	becomes slightly moist below approx 1 ft	6253		SVP167098
	65		6094/6309		SVP167099
	76	becomes slightly moist below approx 2 ft.	6284		SVP167100
	55		6284/6473		SVP167101
	68		6094		SVP167102
	3.5	Borehole terminated			

Recorded By G. Neutzling Date 3/19/14 QA By M. Adamez Date 3/26/14

79

HTRW DRILLING LOG		DISTRICT: St. Louis USACE	HOLE NUMBER SVP 167103
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR: Leidos	
3 PROJECT Coldwater Creek		4 LOCATION # 1763 (HORIZ bound SVP 164075 (D2) 131 FPS)	
5 NAME OF DRILLER David Gruyan / Juan Alvarado		6 MANUFACTURERS DESIGNATION OF DRILL N/A	
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 864989 N 1073753	
9 SURFACE ELEVATION N/A		10 DATE STARTED: 3/19/14	
11 DATE COMPLETED 3/19/14		12 OVERBURDEN THICKNESS N/A	
13 DEPTH DRILLED INTO ROCK: N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A	
14 TOTAL DEPTH OF HOLE 3.5 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A	
17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18 GEOTECHNICAL SAMPLES: N/A	
19 TOTAL NUMBER OF CORE BOXES: N/A		20 SAMPLES FOR CHEMICAL ANALYSIS	
21 TOTAL CORE RECOVERY N/A		22 DISPOSITION OF HOLE	
23 SIGNATURE OF INSPECTOR		24 LOCATION SKETCH/COMMENTS	

LOCATION SKETCH/COMMENTS: and grass plug 3/19/14
COC # LE03202014-02H

Approximately

Recorded By S. Neutzling Date 3/19/14 QA By M. Arduini Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1763
SVP 167103

80

PROJECT Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML	48/6025	-	-	SVP167103 → 1521	-	
	0.5					Both gamma spec		
	1		74/5961	-	-	SVP167104 → 1524	-	> 2x
	1.5					Both gamma spec		
	2		47/5890	-	-	SVP167105 → 1527	-	
	2.5					Iso Th gamma spec		
	3		76/6089	-	-	SVP167106 → 1573	-	> 2x
	3.5					Iso Th gamma spec		
	4	- becomes slightly moist below approx 2 ft	59/6411	-	-	SVP167107 → 1535	-	drier.
	5					Iso Th gamma spec		
	5.5		55/6546	-	-	SVP167108 → 1537	-	
	6					Iso Th gamma spec		
	6.5		67/6364	-	-	SVP167109 → 1532	-	
	7					Iso Th gamma spec		
	7.5	Borehole terminated						(soil)
	8							
	9							
	10							

Recorded By S. Neutzling Date 3/19/14 QA By M. Arduini Date 3/26/14

81

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP167110	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1764 (Horiz bound SVP164075 (D2) (31FPS))			
5. NAME OF DRILLER: Chuck Finkenbain / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865002 N1073776			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 L - 39 cpm		10. DATE STARTED: 3/20/14		11. DATE COMPLETED 3/20/14	
44-10 K - 6363 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 3.5 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
		RAD SAMPLES 7		QA/QC SAMPLES 0	
		ARCHIVE SAMPLE 0		21. TOTAL CORE RECOVERY: N/A	
23. SIGNATURE OF INSPECTOR J. Neutzling		SCALE: None			
LOCATION SKETCH/COMMENTS and grass plug from 3/20/14 CDC #: LE03202014-03H					

Recorded By J. Neutzling Date 3/20/14 QA By M. D. Meyer Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1764
SVP167110

82

PROJECT: Coldwater Creek		INSPECTOR: <u>Co. Neutzling</u>					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sandy, low plasticity, moist - ML	63			SVP167110 0909 Iso Th gamma Spec		
	0.5		6060					
	1		74			SVP167111 0910 gamma Spec Iso Th		
	1.5		6108					
	2		67			SVP167112 0912 Iso Th gamma Spec		
	2.5		6214					
	3		67			SVP167113 0915 Iso Th gamma Spec		
	3.5	becomes slightly moist below ~ 2 ft	6501					
	4		65			SVP167114 0916 Iso Th gamma Spec		slightly drier
	4.5		6781					
	5		76			SVP167115 0917 Iso Th gamma Spec		
	5.5		7172					
	6		49			SVP167116 0919 Iso Th gamma Spec		
	6.5	Borehole terminated	6890					
	7							
	8							
	9							
	10							

Recorded By J. Neutzling Date 3/20/14 QA By M. D. Meyer Date 3/26/14

83

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP167117	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 of 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1771 (Big location downstream from 128FPS toward open inlet)			
5. NAME OF DRILLER: Chuck Finkenbein / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 864954 N1073671			
Meter - Background 44-9 L - 39 cpm 44-10 K - 6363 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 3/20/14			
13. DEPTH DRILLED INTO ROCK N/A		11. DATE COMPLETED 3/20/14			
14. TOTAL DEPTH OF HOLE 0.5 ft bgs		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS		21. TOTAL CORE RECOVERY: N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
LOCATION SKETCH/COMMENTS and grossing plan 3/20/14 COC #: LE03202014-03H		23. SIGNATURE OF INSPECTOR Gary Neutzling		SCALE: None	

Recorded By

G. Neutzling

Date 3/20/14

QA By

M. Anderson

Date

3/24/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1771
SVP167117

84

PROJECT: Coldwater Creek

INSPECTOR:

G. Neutzling

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silt, medium brown, little clay, little v. fine sand, low plasticity, moist - sat	52	-	-	SVP167117 0937 Iso 7 gamma Spec		
	0.5	Borehole terminated.	6131					(soil)
	1.0							
	2.0							
	3.0							
	4.0							
	5.0							
	6.0							
	7.0							
	8.0							
	9.0							
	10.0							

Recorded By

G. Neutzling

Date 3/20/14

QA By

M. Anderson

Date

3/26/14

85

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP169470	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1765 (Horiz Borehole 206 FPS (D3))			
5. NAME OF DRILLER: Todd Keston / Juan Hernandez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865037 N 1075896			
Meter - Background 44-9 L - 33 cpm 44-10 K - 5493 cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 3/20/14 11. DATE COMPLETED 3/20/14			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE 1.5 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/ bentonite		MONITORING N/A	
23. SIGNATURE OF INSPECTOR Gary Neutzling		RAD SAMPLES 3		QA/QC SAMPLES 0	
LOCATION SKETCH/COMMENTS COC #: LE03202014-03H		21. TOTAL CORE RECOVERY: N/A		ARCHIVE SAMPLE 0	

Recorded By Gary Neutzling Date 3/20/14 QA By Mandmeyer Date 3/24/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER • 1765
SVP 169470

86

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sandy low plasticity, moist - ML	70/6174	-	-	SVP169470 1029 Iso Th gamma spec	-	> 2x
	0.5		69/6342	-	-	SVP169471 1030 Iso Th gamma spec	-	> 2x
	1		59/6409	-	-	SVP169472 1033 Iso Th gamma spec	-	
	1.5	Borehole terminated.						(soil)
	2							
	3							
	4							
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/20/14 QA By Mandmeyer Date 3/24/14

87

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 169473	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3 PROJECT Coldwater Creek		4 LOCATION: # 1766 (Using bounding 206 FPS (D3))			
5 NAME OF DRILLER Chuck Furkenbain/Megan Sherman/Jalvance		6 MANUFACTURERS DESIGNATION OF DRILL: N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 865036 N 1075872			
Meter - Background 44-9 L - 38 cpm 44-10 K - 5493 cpm		9 SURFACE ELEVATION N/A			
12 OVERBURDEN THICKNESS N/A		10 DATE STARTED: 3/20/14		11 DATE COMPLETED 3/20/14	
13 DEPTH DRILLED INTO ROCK N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
14 TOTAL DEPTH OF HOLE 1.5 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18 GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19 TOTAL NUMBER OF CORE BOXES N/A		20 SAMPLES FOR CHEMICAL ANALYSIS VOC N/A METALS N/A RAD SAMPLES 3 QA/QC SAMPLES 0 ARCHIVE SAMPLE 0		21 TOTAL CORE RECOVERY: N/A	
22 DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A OTHER (SPECIFY) N/A	
23 SIGNATURE OF INSPECTOR G. Neutzling		SCALE: None			
LOCATION SKETCH/COMMENTS COC #: LE 03202014-03H Soil 3/20/14					

Recorded By

G. Neutzling

Date

3/20/14

QA By

Mandany

Date

3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1766
SVP 169473

88

PROJECT: Coldwater Creek

INSPECTOR:

G. Neutzling

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML	58	-	-	SVP169473 1045 Iso Th gamma spec	-	
	0.5		6323	-	-	SVP169474 1047 Iso Th gamma spec	-	
	1	Clayey SILT, brown, mottled by yellowish brown	52	-	-	SVP169475 1051 Iso Th gamma spec	-	
	1.5	Borehole terminated	5993	-	-		-	
	2		65	-	-		-	
	3		6264	-	-		-	
	4							(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By

G. Neutzling

Date

3/20/14

QA By

Mandany

Date

3/26/14

89

HTRW DRILLING LOG		DISTRICT: St. Louis USACE	HOLE NUMBER SVP 169476
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos	
3. PROJECT: Coldwater Creek		4. LOCATION: #1767 (horiz band 206 FPS (23))	
5. NAME OF DRILLER: Juan Meraado / Hope Saxton		6. MANUFACTURERS DESIGNATION OF DRILL: N/A	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 865061 N 1075885	
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/20/14	
11. DATE COMPLETED: 3/20/14		12. OVERBURDEN THICKNESS: N/A	
13. DEPTH DRILLED INTO ROCK: N/A		14. TOTAL DEPTH OF HOLE: 1.5 ft bgs	
15. DEPTH GROUNDWATER ENCOUNTERED: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A	
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS: N/A	
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE: Backfill using bentonite	
23. SIGNATURE OF INSPECTOR: Gary Neutzling		24. SCALE: None	
LOCATION SKETCH/COMMENTS: w/ grass plug, 3/20/14 COC #: LE 03282014-03H			

Recorded By G. Neutzling Date 3/20/14 QA By Mandel Myers Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1767
SVP 169476

90

PROJECT: Coldwater Creek		INSPECTOR: G Neutzling		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
0	54/5662	SILT, brown, little clay, little v. fine sand, low plasticity, moist - ML				SVP 169476 1255 Iso Th gamma spec		
0.5	70/6108					SVP 169477 1256 Iso Th gamma spec		>2x
1	55/6973					SVP 169478 1257 Iso Th gamma spec		
1.5		Borehole terminated						soil
2								
5								
6								
7								
8								
9								
10								

Recorded By G. Neutzling Date 3/20/14 QA By Mandel Myers Date 3/26/14

91

HTRW DRILLING LOG		DISTRICT St. Louis USACE	HOLE NUMBER SVP169479
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos	
3. PROJECT: Coldwater Creek		4. LOCATION # 1768 (Hwy bound SVP162362 @ 4)	
5. NAME OF DRILLER: Juan Alvarado / Hope Sexton		6. MANUFACTURERS DESIGNATION OF DRILL: N/A	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864952 N 1075896	
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 3/20/14	
11. DATE COMPLETED: 3/20/14		12. OVERBURDEN THICKNESS: N/A	
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A	
16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A	
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES: N/A	
20. SAMPLES FOR CHEMICAL ANALYSIS VOC: N/A METALS: N/A RAD SAMPLES: 2 QA/QC SAMPLES: 0 ARCHIVE SAMPLE: 0		21. TOTAL CORE RECOVERY: N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		23. SIGNATURE OF INSPECTOR G. Neutzling	
LOCATION SKETCH/COMMENTS CGC #: LE03212014-01H and grossing 3/20/14 SCALE: None			

Recorded By G. Neutzling Date 3/20/14 QA By Wandinger Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1768
SVP169479

92

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little y. fine sand, low plasticity, moist	72			SVP169479		
	0.5		5931			1214 Iso Th gamma spec		>2X
	1.0	Borehole terminated	55			SVP169480		
	1.0		6123			1215 Iso Th gamma spec		soil
	2							
	3							
	4							
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 3/20/14 QA By Wandinger Date 3/26/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 169481	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 1769 (Hwy bound SVP162362 (D4))			
5. NAME OF DRILLER Juan Alvarado/Hope Sartori		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864976 N1075896			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 L - 33 cpm		10. DATE STARTED: 3/20/14		11. DATE COMPLETED 3/20/14	
44-10 K - 5493 cpm		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE 1.5 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING WELL	
Backfill using bentonite		w/bentonite		N/A	
19. TOTAL NUMBER OF CORE BOXES: N/A		RAD SAMPLES		QA/QC SAMPLES	
		2		1	
23. SIGNATURE OF INSPECTOR		OTHER (SPECIFY)		ARCHIVE SAMPLE	
Gary Reutzel		N/A		N/A	
LOCATION SKETCH/COMMENTS COC #: LE03212014-01H					
SCALE: None					

Recorded By L. Huntzberg Date 3/24/14 QA By W. Adams Date 3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER	1769
SVP	169481

PROJECT: Coldwater Creek			INSPECTOR: G. Neufeld			SHEET 2 of 2		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	69 / 5885	-	-	SVP169481 1310 IsoTh gamma spec	-	go deeper!
	0.5		66 / 6077	-	-	SVP169482 1312 IsoTh gamma spec	-	
	1		50 / 6086	-	-	Archive 1332 IsoTh gamma spec	-	
	1.5	Borehole terminated						(soil)
	4							
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By L. Neutzel Date 3/20/14 QA By Manday Date 3/26/14

97

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP169483	
1 COMPANY NAME: Leidos		2 DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3 PROJECT: Coldwater Creek		4 LOCATION # 1770 (Horiz bound SVP 162362 (P4) 100 1132)			
5 NAME OF DRILLER: Juan Alvarado / Hope Sexton		6 MANUFACTURERS DESIGNATION OF DRILL: N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 864964 N1075871			
Meter - Background 44-9 L - 33 cpm 44-10 A - 5493 cpm		9 SURFACE ELEVATION: N/A			
12 OVERBURDEN THICKNESS: N/A		10 DATE STARTED: 3/20/14			
13 DEPTH DRILLED INTO ROCK: N/A		11 DATE COMPLETED: 3/20/14			
14 TOTAL DEPTH OF HOLE: 1.0 ft		15 DEPTH GROUNDWATER ENCOUNTERED: N/A			
16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A		17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18 GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS		21. TOTAL CORE RECOVERY: N/A	
N/A		VOC		METALS	
N/A		RAD SAMPLES		QA/QC SAMPLES	
N/A		ARCHIVE SAMPLE		22. DISPOSITION OF HOLE	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		SCALE: None			
LOCATION SKETCH/COMMENTS COC #: LE03212014-01H					

Recorded By

J. Neutzling

Date

3/20/14

QA By

M. Neutzling

Date

3/26/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER
SVP169483

1770

SHEET 2 of 2

PROJECT: Coldwater Creek

INSPECTOR:

G. Neutzling

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	SILT, medium brown, little clay, little v. fine sandy, low plasticity, moist - ML	54			SVP169483		
	0.5		5769			1326		
	1.0	Borehole terminated	61			SVP169484		
	1.5		5672			1327		
	2.0					ISO Th gamma spec		
	3.0							
	4.0							
	5.0							
	6.0							
	7.0							
	8.0							
	9.0							
	10.0							

Recorded By

J. Neutzling

Date

3/20/14

QA By

M. Neutzling

Date

3/26/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVPI61971	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 of 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 961 (systematic array)			
5. NAME OF DRILLER: Matt Dostal / Antonio Martinez, Rick Whitney		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865173 N107402519			
9. SURFACE ELEVATION N/A		10. DATE STARTED 4/1/14			
11. DATE COMPLETED 4/1/14		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
15. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A		16. TOTAL DEPTH OF HOLE 2.0 ft bgs			
17. GEOTECHNICAL SAMPLES N/A		18. TOTAL NUMBER OF CORE BOXES N/A			
19. SAMPLES FOR CHEMICAL ANALYSIS N/A		20. TOTAL CORE RECOVERY N/A			
21. DISPOSITION OF HOLE Backfill using bentonite		22. SIGNATURE OF INSPECTOR G. Neutzling			
LOCATION SKETCH/COMMENTS COC# : LE04022014-01H					

Recorded By G. Neutzling Date 4/1/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG (Continuation Sheet)				HOLE NUMBER 961	
PROJECT: Coldwater Creek				INSPECTOR: G. Neutzling	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Remarks
	0	Clayey SILT, med brown, little v. fine sandy low plasticity, moist ML	61/7795		SVP161971 1453 IsoTh gamma spec
	0.5		64/8021		SVP161972 1455 IsoTh gamma spec
	1.0		53/7906		1457
	1.5		45/7908		Archive 1500 IsoTh gamma spec
	2.0	Borehole terminated			(Soil)
	5				
	6				
	7				
	8				
	9				
	10				

Recorded By G. Neutzling Date 4/1/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP161976	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 964 (systematic array) soil			
5. NAME OF DRILLER Adam Queen / Antonio Martinez / Juan Alvarado		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES Q 812-15-14 E 865155 N1074056			
Meter - Background 44-9 F - 29 cpm 44-10 I - 6211 cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED 4/8/14 11. DATE COMPLETED: 4/8/14			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18. GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
23. SIGNATURE OF INSPECTOR G. Neutzling		RAD SAMPLES 4		QA/QC SAMPLES 1 set of 2	
21. TOTAL CORE RECOVERY N/A		ARCHIVE SAMPLE 1		OTHER (SPECIFY) N/A	
LOCATION SKETCH/COMMENTS COC#: LE04082014102H 4/8/14 SCALE: None					

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 964
SVP161976

SHEET 2 of 2

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling				SHEET 2 of 2		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silty CLAY, med brown, trace fine sand, low plasticity moist - CL	54/6815	-	-	SVP161976 0806 IsoTh gamma spec	-	Collected as per soil samples SVP161976-1 SVP161976-2
	0.9	Clayey SILT, brown, little v. fine sand, low plasticity moist - ML	56/6491	-	-	0809	-	
	1		60/6765	-	-	SVP161977 0811 IsoTh gamma spec	-	
	2		55/6588	-	-	0815	-	drier
	3		60/6626	-	-	0817	-	
	4		60/6755	-	-	SVP161978 0819 IsoTh gamma spec	-	
	5		66/6815	-	-	0840	-	
	6		65/6607	-	-	0842	-	
	7		44/6573	-	-	0844	-	
	8		52/6712	-	-	MS 4/17/14 0847 0847	-	
	9		60/6526	-	-	SVP161979 0849 IsoTh gamma spec	-	
	10		47/6755	-	-	Archive 0837 IsoTh gamma spec	-	
	11	Borehole terminated						soil

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 161985	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: #968 (systematic array) soil			
5. NAME OF DRILLER: Adam Queen/Antonio Martinez/Alexander		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl/s trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: 85 03 12-15-14 E 865173 N10740874			
Meter - Background 44-9 P - 29 cpm 44-10 I - 6211 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS: N/A		VOC: N/A		METALS: N/A	
22. DISPOSITION OF HOLE: Backfill using bentonite		BACKFILLED: w/bentonite		MONITORING: N/A	
23. SIGNATURE OF INSPECTOR: Gary Neutzling		RAD SAMPLES		QA/QC SAMPLES	
LOCATION SKETCH/COMMENTS: Soil 4/8/14 COC#: L504082014-02H		ARCHIVE SAMPLE		21. TOTAL CORE RECOVERY: N/A	
Approximately		SCALE: None			

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP 161985		968	
PROJECT: Coldwater Creek			INSPECTOR: G. Neutzling		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample
	0	Silty CLAY, medium brown, trace v. fine sand, low plasticity, moist - CL	52/6613	-	-	SVP 161985 0909 Iso Th gamma spec
	0.5		48/6591	-	-	0910
	1		61/6782	-	-	SVP 161986 0912 Iso Th gamma spec
	1.5		52/6326	-	-	Archive 0905 Iso Th gamma spec
	2	Borehole terminated				
	5					
	6					
	7					
	8					
	9					
	10					

Soil

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP 161990	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 971 (systematic amwg) soil			
5. NAME OF DRILLER: Adam Queen / Antonio Martinez / Juan Hernandez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES QB 12-15-14 E 8651552N 107414805			
Meter - Background rerun bkgnd ~1100		9. SURFACE ELEVATION N/A			
44-9 F - 29 cpm 35 cpm		10. DATE STARTED 4/8/14			
44-10 I - 621 cpm 6331 cpm		11. DATE COMPLETED 4/8/14			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 7.5 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		RAD SAMPLES	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		21. TOTAL CORE RECOVERY N/A		23. SIGNATURE OF INSPECTOR	
LOCATION SKETCH/COMMENTS		SCALE: None		23. SIGNATURE OF INSPECTOR	
COG #: LE04082014-02H		SCALE: None		23. SIGNATURE OF INSPECTOR	

Recorded By J. Neutzling Date 4/8/14 QA By Megan Sherman Date 4-17-14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP 161990		SHEET 2 of 2			
PROJECT Coldwater Creek			INSPECTOR: G. Neutzling					
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silty CLAY, med-brown, trace fine sand, moderate to low plasticity, moist - CL	53/6449	-	-	SVP161990 0939	-	IsoTh gamma spec
	1		51/6524	-	-	0941	-	
	1.8		72/6501	-	-	SVP161991 0942	-	IsoTh gamma spec
	2	Clayey SILT, grayish brown, little v. fine sand, low plasticity, moist	57/6824	-	-	0944	-	
	2		52/6855	-	-	0950	-	
	3		50/6605	-	-	0952	-	
	3		62/6856	-	-	SVP161992 1000	-	IsoTh gamma spec
	4	becomes slightly moist below approx 3 1/2 ft	42/5988	-	-	1003	-	dry (damp)
	4		59/6751	-	-	1006	-	dry
	5		57/6824	-	-	1009	-	
	5		67/6974	-	-	SVP161993 1013	-	IsoTh gamma spec
	6		63/6918	-	-	0957	-	go deeper!
	6		81/6845	-	-	SVP1619518 1023	-	damp
	7		71/7180	-	-	1043	-	
	7.5		60/6758	-	-	Archive 1100	-	60, 71, 69
	7.5	Borehole terminated				IsoTh gamma spec		
	8							soil
	9							
	10							

Recorded By J. Neutzling Date 4/8/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP161996	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT Coldwater Creek		4 LOCATION # 974 (systematic amwg) soil			
5 NAME OF DRILLER Juan Alvarado/Antonia Martinez/Adam		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss bowl, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES @ B 12-15-14 E 8651386 N10741492			
Meter - Background 44-9 F - 41 cpm 44-10 I - 5964 cpm		9 SURFACE ELEVATION N/A			
12 OVERBURDEN THICKNESS N/A		10 DATE STARTED 4/8/14 11 DATE COMPLETED 4/8/14			
13 DEPTH DRILLED INTO ROCK N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18. GEOTECHNICAL SAMPLES: N/A		19 TOTAL NUMBER OF CORE BOXES N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		21 TOTAL CORE RECOVERY: N/A			
N/A		N/A			
22 DISPOSITION OF HOLE		23 SIGNATURE OF INSPECTOR			
Backfill using bentonite		w/bentonite N/A			
LOCATION SKETCH/COMMENTS COC #: LEO4092014-02H SCALE: None					

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 974
SVP161996

PROJECT Coldwater Creek		INSPECTOR: G. Neutzling				SHEET 2 of 2		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Silty CLAY, medium brown, trace v. fine sand, low plasticity, moist - CL	57/6465	-	-	SVP161996 1443 Iso Th gamma spec		
	0.5		66/6615	-	-	SVP161997 1445 Iso Th gamma spec		
	1.5		56/6687	-	-	1447		
	2.0	Borehole terminated	56/6565	-	-	Archive 1440 Iso Th gamma spec		
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 4/8/14 QA By Megan Sherman Date 4/17/14

Recorded By J. Neutzing Date 4/8/14 QA By Megan Sherman Date 4/17/14

Recorded By L. Neutzelung Date 4/8/14 QA By Meyers Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP162010	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 981			
5. NAME OF DRILLER: <i>Alan Queen / Antonio Martinez / Juan Alvarez</i>		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES QB 12-15-14 E 865103 N 10742+07			
Meter - Background 44-9 P - 41 cpm 44-10 I - 5964 cpm		9. SURFACE ELEVATION: N/A			
12. OVERBURDEN THICKNESS: N/A		10. DATE STARTED: 4/8/14		11. DATE COMPLETED: 4/8/14	
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
LOCATION SKETCH/COMMENTS Soil <i>4/8/14</i> COC #: LEO4092014-024		RAD SAMPLES		QA/QC SAMPLES	
		2		1	
		OTHER (SPECIFY)		23. SIGNATURE OF INSPECTOR <i>G. Neutzling</i>	
		N/A		SCALE: None	

Recorded By *G. Neutzling* Date *4/8/14* QA By *Morgan Sherman* Date *4/17/14*

HTRW DRILLING LOG (Continuation Sheet)				HOLE NUMBER SVP162010 981	
PROJECT: Coldwater Creek		INSPECTOR: <i>G. Neutzling</i>		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
0		Clayey SILT, med brown mottled by brown, little v. fine sand, low plasticity, very moist - ML	67		
0.5			7094		
1					
1.5					
2					
2.5					
3					
3.5					
4					
4.5					
5					
5.5					
6					
6.5					
7					
7.5					
8					
8.5					
9					
9.5					
10					

67 / 7094

55 / 6586

60 / 7071

59 / 6965

2.0

Borehole terminated

SVP162010 1527 IsoTh gamma spec

SVP162011 1533 IsoTh gamma spec

Archive 1524 IsoTh gamma spec

Soil

4/8/14

Recorded By *G. Neutzling* Date *4/8/14* QA By *Morgan Sherman* Date *4/17/14*

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP161983	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 967 (systematic array) soil			
5. NAME OF DRILLER Adam Queen / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss bowl, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES Q 8 12-15-14 E 865138-45 N 1074088			
9. SURFACE ELEVATION N/A		10. DATE STARTED 4/9/14			
11. DATE COMPLETED 4/9/14		12. OVERBURDEN THICKNESS N/A			
13. DEPTH DRILLED INTO ROCK N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
15. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
17. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
18. TOTAL NUMBER OF CORE BOXES N/A		VOC		METALS	
19. RAD SAMPLES		QA/QC SAMPLES		ARCHIVE SAMPLE	
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		BACKFILLED		MONITORING	
21. DISPOSITION OF HOLE		Backfill using bentonite		w/bentonite	
22. LOCATION SKETCH/COMMENTS		Soil 4/9/14		SCALE: None	
CUC#: LE04092014-03 H					

Recorded By J. Neutzling Date 4/9/14 QA By Meyan Sherman Date 4-17-14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP161983		SHEET 2 of 2	
PROJECT: Coldwater Creek			INSPECTOR <u>G. Neutzling</u>		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample
						Blow Counts
						Remarks
	0	Clayey SILT, medium grayish brown, little v. fine sandy, low plasticity, moist - ML	55	-	-	SVP161983
	0.5		8731	-	-	0830
	1			-	-	0832
	1.5		51	-	-	0834
	2		8521	-	-	0834
	2.5		52	-	-	0834
	3		8457	-	-	0834
	3.5		79	-	-	0828
	4		8016	-	-	0828
	4.5			-	-	0828
	5			-	-	0828
	6			-	-	0828
	7			-	-	0828
	8			-	-	0828
	9			-	-	0828
	10			-	-	0828
		Borehole terminated				Soil

Recorded By J. Neutzling Date 4/9/14 QA By Meyan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP162012	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 982 (systematic array) soil			
5. NAME OF DRILLER: Adam Queen / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: AS 12-15-14 E 865138.7 N 107421.7			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 4/9/14			
11. DATE COMPLETED: 4/9/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR: Gary Neutzling		24. SCALE: None			
LOCATION SKETCH/COMMENTS: Soil bgs 4/9/14 COC #: LE04092014-03H					

Recorded By G. Neutzling Date 4/9/14 QA By Meyan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP162012 982	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID
	0	Clayey SILT, med, brown, little v. fine sand, low plasticity, moist - ML	70/8897	—
	0.5		62/8901	—
	1		73/9032	—
	1.5		81/9134	—
	2	Borehole terminated		
	5			
	6			
	7			
	8			
	9			
	10			

Recorded By G. Neutzling Date 4/9/14 QA By Meyan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP 162017	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT Coldwater Creek		4 LOCATION # 985 (systematic armwg) soil			
5 NAME OF DRILLER Adam Green / Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES @ 8 12-15-14 E 8651283 N 1074242 36			
Meter - Background 44-9 L - 43 cpm 44-10 I - 8306 cpm		9 SURFACE ELEVATION N/A			
12 OVERBURDEN THICKNESS N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
13 DEPTH DRILLED INTO ROCK N/A		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18 GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20 SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22 DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
23 SIGNATURE OF INSPECTOR		SCALE: None		21 TOTAL CORE RECOVERY: N/A	
LOCATION SKETCH/COMMENTS Soil 4/9/14 LOC #: LE04092014-03H					

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)				HOLE NUMBER 985	
PROJECT Coldwater Creek		INSPECTOR: G. Neutzling		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	100/8764	-	-
	0.5		62/8847	-	-
	1.0		59/8721	-	-
	1.5		61/8628	-	-
	2.0	Borehole terminated			
	5				
	6				
	7				
	8				
	9				
	10				

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162032	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 992 (systematic annular) soil			
5. NAME OF DRILLER: Adam Queen / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 065138 N1074273			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 4/9/14			
11. DATE COMPLETED: 4/9/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR		24. LOCATION SKETCH/COMMENTS			
Backfill using bentonite		COC #: LE04092014-03H			

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER
SVP 162032 992

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling				SHEET: 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts
0	0	Clayey SILT, mal brown, little v. fine sandy low plasticity, moist - ML	63/8776	-	-	SVP162032 1006 Iso Th gamma spec	0
0.5	0.5		87/8768			SVP162032 1007 Iso Th gamma spec	0.5
1	1		60/8617			1009	1
1.5	1.5		66/8638			Archive 1011 Iso Th gamma spec	1.5
2.0	2.0	Borehole terminated					2
5	5						5
6	6						6
7	7						7
8	8						8
9	9						9
10	10						10

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162030	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT: Coldwater Creek		4 LOCATION # 991 (Braided TD/systematic auger)			
5 NAME OF DRILLER Todd Keeton/Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 865103 N1074279			
Meter - Background 44-9 L - 42 cpm 44-10 E - 8358 cpm		9 SURFACE ELEVATION N/A			
12 OVERBURDEN THICKNESS N/A		10 DATE STARTED 4/9/14 11 DATE COMPLETED 4/9/14			
13 DEPTH DRILLED INTO ROCK: N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
18 GEOTECHNICAL SAMPLES N/A		19 TOTAL NUMBER OF CORE BOXES N/A			
20 SAMPLES FOR CHEMICAL ANALYSIS N/A		21 TOTAL CORE RECOVERY N/A			
22 DISPOSITION OF HOLE Backfill using bentonite		23 SIGNATURE OF INSPECTOR G. Neutzling			
LOCATION SKETCH/COMMENTS COC #: LE04102014-014 Soil 4/9/14 SCALE: None					

Recorded By G. Neutzling Date 4/9/14 QA By _____ Date _____

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 991
SVP 162030

PROJECT: Coldwater Creek

INSPECTOR: GN

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	54/8779	-	-	SVP162030 1304 IsoTh gamma spec	-	Listed as TD but not collect ex/for suspect ID is location 0.5 ft bgs 4/9/14
	0.5		70/8547	-	-	SVP162031 1306 IsoTh gamma spec	-	Same
	1		61/8744	-	-	1307	-	
	1.5		67/8614	-	-	Archive 1303 IsoTh gamma spec	-	Archive Submitted 4/9/14 SVP174764 3/24/15 22
	2	Borehole Terminated						Soil
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 4/9/14 QA By Megane Sherman Date 4/17/14

51

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP 162038	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT Coldwater Creek		4 LOCATION # 996 (systematic auger) soil			
5 NAME OF DRILLER Todd Keaton / Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 865120 N1074304			
Meter - Background		9 SURFACE ELEVATION N/A			
44-9 L - 42 cpm		10 DATE STARTED 4/9/14		11 DATE COMPLETED 4/9/14	
44-10 I - 8358 cpm		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
12 OVERBURDEN THICKNESS N/A		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
13 DEPTH DRILLED INTO ROCK: N/A		17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		19 TOTAL NUMBER OF CORE BOXES N/A			
18 GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20 SAMPLES FOR CHEMICAL ANALYSIS		VOC	METALS	RAD SAMPLES	QA/QC SAMPLES
N/A		N/A	N/A	2	0
22 DISPOSITION OF HOLE		BACKFILLED	MONITORING	OTHER (SPECIFY)	23 SIGNATURE OF INSPECTOR
Backfill using bentonite		w/bentonite	N/A	N/A	Scale: None
LOCATION SKETCH/COMMENTS COC #: LE0410 2014-01H Soil 4/9/14					

Recorded By S. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 996
SVP 162038

PROJECT: Coldwater Creek

INSPECTOR: G. Neutzling

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sandy low plasticity	61/8751	—	—	SVP162038 1315 130th gamma spec	—	
	0.5		77/8488	—	—	SVP162039 1316 130th gamma spec	—	
	1		61/8645	—	—	1317	—	
	1.5		63/8783	—	—	Archive 1318 130th gamma spec	—	Archive Submitted 4/9/14 SVP174765 3/24/15 PR
	2	Borehole terminated						(Soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By S. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 995 (systematic among) Soil			
5. NAME OF DRILLER Todd Keaton/Antonio Mart		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865085 N1074304			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 L - 42 cpm		10. DATE STARTED 4/9/14			
44-10 I - 8358 cpm		11. DATE COMPLETED 4/9/14			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		RAD SAMPLES	
N/A		N/A		N/A	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
LOCATION SKETCH/COMMENTS		23. SIGNATURE OF INSPECTOR		SCALE: None	
COC#: LE04102014-01H		G. Neutzling			

Approximately

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER 995	
PROJECT Coldwater Creek			INSPECTOR G. Neutzling	
DESCRIPTION OF MATERIALS			449 NAI	PID
Clayey SILT, med brown, little v. fine sandy, low plasticity, moist - ML			60/8495	-
Silty CLAY, med brown, trace sand, low plasticity, moist - CL			50/8631	-
Borehole terminated			61/8729	-

Depth (ft bgs)	Recovery	Analytical Sample	Blow Counts	Remarks
0	-	SVP 162036	-	1330
0.5	-	1331	-	1330
1	-	1332	-	1330
1.5	-	1333	-	1330
2	-	1334	-	1330
3	-	1335	-	1330
4	-	1336	-	1330
5	-	1337	-	1330
6	-	1338	-	1330
7	-	1339	-	1330
8	-	1340	-	1330
9	-	1341	-	1330
10	-	1342	-	1330

Recorded By G. Neutzling Date 4/9/14 QA By Meyen Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162046	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 of 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1000 (systematic array) soil			
5. NAME OF DRILLER: Todd Kustin / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowl, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES R 865103 N 1074335			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 4/9/14			
11. DATE COMPLETED: 4/9/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		14. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
15. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		16. TOTAL DEPTH OF HOLE: 20 ft bgs			
17. GEOTECHNICAL SAMPLES: N/A		18. TOTAL NUMBER OF CORE BOXES: N/A			
19. SAMPLES FOR CHEMICAL ANALYSIS: N/A		20. TOTAL CORE RECOVERY: N/A			
21. DISPOSITION OF HOLE: BACKFILLED		22. SIGNATURE OF INSPECTOR: Gary Neutzling			
23. BACKFILL using bentonite		24. SCALE: None			
LOCATION SKETCH/COMMENTS: Soil 4/9/14 COC#: LE04102014-01H					

Recorded By G. Neutzling Date 4/9/14 QA By Morgan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER SVP 162046	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling	
449 NAI		PID	
Recovery		Analytical Sample	
Blow Counts		Remarks	
USCS	Depth (ft bgs)	Description of Materials	Remarks
	0	Clayey Silty, medium brown, little v. fine sandy, low plasticity, moist - Mz	SVP 162046 1341 IsoTh gamma spec
	0.5		Same
	1		
	1.5		
	2		
	3		
	4		
	5		
	6		
	7		
	8		
	9		
	10		

Recorded By G. Neutzling Date 4/9/14 QA By Morgan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT Coldwater Creek		4 LOCATION #999 (systematic augur) soil			
5 NAME OF DRILLER: Todd Keston / Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL: N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES QB 12-15-14 E 86506873 N10743351			
Meter - Background 44-9 L - 42 cpm 44-10 I - 8358 cpm		9 SURFACE ELEVATION N/A			
12 OVERBURDEN THICKNESS N/A		10 DATE STARTED 4/9/14 11 DATE COMPLETED 4/9/14			
13 DEPTH DRILLED INTO ROCK: N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
14 TOTAL DEPTH OF HOLE 6.0 ft bgs		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A		18 GEOTECHNICAL SAMPLES: N/A			
20 SAMPLES FOR CHEMICAL ANALYSIS N/A		DISTURBED VOC N/A		UNDISTURBED METALS N/A	
21 TOTAL CORE RECOVERY: N/A		RAD SAMPLES 4		QA/QC SAMPLES 0	
22 DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
23 SIGNATURE OF INSPECTOR G. Neutzling		ARCHIVE SAMPLE 1		OTHER (SPECIFY) N/A	
LOCATION SKETCH/COMMENTS COC #: LE04102014-01H SCALE: None					

Recorded By G. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		HOLE NUMBER 999		SVP 162042		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks	
	0	Clayey SILT, medium brown, little v. fine sand, low plasticity, moist - ML	74/8669	-	-	SVP162042 1418	-		
	1		74/8638	-	-	SVP162043 1419	-		
	1		67/8513	-	-	1421	-		
	2		70/8634	-	-	1422	-		
	2		57/8625	-	-	1428	-		
	3	Silty CLAY, medium brown, trace v. fine sand, moderately plastic, moist - CL	59/8615	-	-	1430	-	LL mid to upper 40's	
	3		63/8811	-	-	1431	-		
	4		64/8909	-	-	SVP162044 1433	-		
	4		54/8806	-	-	1438	-		
	5		61/8557	-	-	1439	-		
	5		71/8826	-	-	SVP162045 1440	-		
	6.0		67/8786	-	-	1441	-		
	6.0	Borehole terminated						(soil)	
	7								
	8								
	9								
	10								

Recorded By G. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162051	
1 COMPANY NAME Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 of 2	
3 PROJECT Coldwater Creek		4 LOCATION # 1003 (systematic array) soil			
5 NAME OF DRILLER Todd Keeton / Antonio Martinez		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss towel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES E 865085 N 1074366			
Meter - Background		9 SURFACE ELEVATION N/A			
44-9 L - 42 cpm		10 DATE STARTED 4/9/14		11 DATE COMPLETED 4/9/14	
44-10 I - 8358 cpm					
12 OVERBURDEN THICKNESS N/A		15 DEPTH GROUNDWATER ENCOUNTERED N/A			
13 DEPTH DRILLED INTO ROCK N/A		16 DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14 TOTAL DEPTH OF HOLE 2.0 ft bgs		17 OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18 GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
19. TOTAL NUMBER OF CORE BOXES N/A					
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		METALS	
N/A		N/A		N/A	
21 TOTAL CORE RECOVERY N/A		RAD SAMPLES		QA/QC SAMPLES	
N/A		2		0	
22 DISPOSITION OF HOLE		BACKFILLED		MONITORING	
Backfill using bentonite		w/bentonite		N/A	
23. SIGNATURE OF INSPECTOR		G. Neutzling			
LOCATION SKETCH/COMMENTS		SCALE: None			
Soil 4/9/14 COC #: LEO4102014-01H					

Recorded By G. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP 162051		SHEET 2 of 2	
PROJECT Coldwater Creek			INSPECTOR G. Neutzling			
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample
						Blow Counts
						Remarks
	0	Clayey SILT, med brown, little v. fine sandy low plasticity, moist - ML	60/8880	—	—	SVP162051 1449 Iso Ph gamma spec
	0.5		73/8678	—	—	SVP162052 1450 Iso Ph gamma spec
	1		52/8622	—	—	1451
	1.5		54/8921	—	—	Archive 1452 Iso Ph gamma spec
	2	Borehole terminated				Soil
	5					
	6					
	7					
	8					
	9					
	10					

Recorded By G. Neutzling Date 4/9/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP162056	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1006 (systematic among) soil			
5. NAME OF DRILLER: Todd Kerton / Antonio Martinez		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss bowl, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 865068 N1074397			
Meter - Background 44-9 L - 42 cpm 44-10 I - 8358 cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 4/9/14 11. DATE COMPLETED: 4/9/14			
13. DEPTH DRILLED INTO ROCK N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		DISTURBED VOC N/A		UNDISTURBED METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite		MONITORING N/A	
23. SIGNATURE OF INSPECTOR G. Neutzel		RAD SAMPLES 4		QA/QC SAMPLES 1 set of 2	
21. TOTAL CORE RECOVERY N/A		ARCHIVE SAMPLE 1		OTHER (SPECIFY) N/A	
LOCATION SKETCH/COMMENTS COC #: LE04102014-01H					

Recorded By G. Neutzel Date 4/9/14 QA By Megan Shuman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER SVP162056		SHEET 2 of 2	
PROJECT: Coldwater Creek			INSPECTOR: G. Neutzel		REMARKS	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Analytical Sample	Blow Counts
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	63/8742	-	SVP162056-1457	1457
	1		50/8472	-	1458	1458
	2		63/8403	-	1459	1459
	3		67/8572	-	SVP162057-1500	1500
	4	Silty CLAY, med brown, trace v. fine sand, moderate plasticity, moist - CL	66/8482	-	1505	1505
	5		72/8613	-	1507	1507
	6		73/8583	-	1508	1508
	7		96/8682	-	SVP162058-1511	1511
	8		70/8544	-	1518	1518
	9		84/8886	-	1521	1521
	10		87/8768	-	SVP162059-1522	1522
	11		59/8816	-	Archive 1519	1519
	12	Borehole terminated				
	13					
	14					
	15					
	16					
	17					
	18					
	19					
	20					
	21					
	22					
	23					
	24					
	25					
	26					
	27					
	28					
	29					
	30					

Recorded By G. Neutzel Date 4/9/14 QA By Megan Shuman Date 4/17/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162063	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: #1009 (systematic array) soil			
5. NAME OF DRILLER: David G. Neutzling / Juan Alvarado / Rick Whitley		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: 0812-15-14 E 8650502 N 107442819			
Meter - Background		9. SURFACE ELEVATION: N/A			
44-9 F - 45 cpm 44-10 I - 8367 cpm		10. DATE STARTED: 4/10/14		11. DATE COMPLETED: 4/10/14	
12. OVERBURDEN THICKNESS: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS: N/A		VOC	METALS	RAD SAMPLES	QA/QC SAMPLES
		N/A	N/A	2	0
22. DISPOSITION OF HOLE: Backfill using bentonite		BACKFILLED	MONITORING	OTHER (SPECIFY)	23. SIGNATURE OF INSPECTOR: David G. Neutzling
		w/bentonite	N/A	N/A	
LOCATION SKETCH/COMMENTS: soil 4/17/14 COC#: LEO4102014-07H					

Recorded By: G. Neutzling Date: 4/10/14 QA By: Megan Shuman Date: 4/17/14

HTRW DRILLING LOG (Continuation Sheet)			HOLE NUMBER: 1009 SVP 162063	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID
	0	Clayey SILT, medium brown, little v. fine sandy low plasticity, moist. - ML	86	
	0.5		85A2	
	1		66	
	1.5		8649	
	2		69	
	2.5		8628	
	3		75	
	3.5		8648	
	4	Borehole terminated		
	5			
	6			
	7			
	8			
	9			
	10			

Recorded By: G. Neutzling Date: 4/10/14 QA By: Megan Shuman Date: 4/17/14

65

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP162049	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1002 (systematic auger) soil			
5. NAME OF DRILLER: David Guyan/Juan Alvarado/Rick Whitney		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: E 865050 N1074366			
Meter - Background		9. SURFACE ELEVATION: N/A			
44-9 F - 45 cpm		10. DATE STARTED 4/10/14			
44-10 I - 8367 cpm		11. DATE COMPLETED 4/10/14			
12. OVERBURDEN THICKNESS: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS: N/A		VOC: N/A		METALS: N/A	
22. DISPOSITION OF HOLE: Backfill using bentonite		BACKFILLED: w/bentonite		MONITORING: N/A	
23. SIGNATURE OF INSPECTOR: Gary Neutzling		RAD SAMPLES: 2		QA/QC SAMPLES: 0	
LOCATION SKETCH/COMMENTS: Soil from 4/10/14		SCALE: None		19. TOTAL NUMBER OF CORE BOXES: N/A	

Recorded By G. Neutzling Date 4/10/14 QA By Megan Shuman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1002
SVP 162049

PROJECT Coldwater Creek		INSPECTOR G. Neutzling					SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	71/8318	-	-	SVP162049 0810 IsoTh gamma spec	-	
	0.5	Silty CLAY, medium brown, trace v. fine sand, moderate plasticity, moist - CL	54/8427	-	-	0811	-	LL med to upper 40s
	1.0		57/8531	-	-	0812	-	
	1.5		68/8621	-	-	SVP162050 0813 IsoTh gamma spec	-	
	2.0	Borehole terminated						(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 4/10/14 QA By Megan Shuman Date 4/17/14

67

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP162068	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1012 (systematic array) soil			
5. NAME OF DRILLER: David Guyan/Juan Alvarado/Rick Whitman		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: Q812-15-14 E 8650337 N10744584			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 4/10/14			
11. DATE COMPLETED: 4/10/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS			
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE			
23. SIGNATURE OF INSPECTOR: Gary Neutzhing		24. LOCATION SKETCH/COMMENTS			
25. SCALE: None		26. COG #: LE 04102014-0711			

Recorded By G. Neutzhing Date 4/10/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1012
SVP 162068

SHEET 2 of 2

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzhing					REMARKS	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - ML	66/8527	-	-	SVP162068 0824 Iso Th gamma Spec	-	
	0.5		62/8776	-	-	0826	-	
	1		67/8405	-	-	SVP162069 0833 Iso Th gamma Spec	-	
	1.5		46/8716	-	-	Archive 0835 Iso Th gamma Spec	-	
	2.0	Borehole terminated						(Soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzhing Date 4/10/14 QA By Megan Sherman Date 4/17/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE	HOLE NUMBER SVP162307
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos	
3. PROJECT Coldwater Creek		4. LOCATION # 1104 (systematic auger) soil	
5. NAME OF DRILLER <i>Adam G. Grier</i>		6. MANUFACTURERS DESIGNATION OF DRILL N/A	
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864945 N 107554435	
9. SURFACE ELEVATION N/A		10. DATE STARTED: 4/17/14	
11. DATE COMPLETED: 4/17/14		12. OVERBURDEN THICKNESS N/A	
13. DEPTH DRILLED INTO ROCK N/A		14. TOTAL DEPTH OF HOLE 2.0 ft bgs	
15. DEPTH GROUNDWATER ENCOUNTERED N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A	
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES N/A	
19. TOTAL NUMBER OF CORE BOXES: N/A		20. SAMPLES FOR CHEMICAL ANALYSIS	
21. TOTAL CORE RECOVERY: N/A		22. DISPOSITION OF HOLE	
23. SIGNATURE OF INSPECTOR <i>G. Neutzling</i>		24. BACKFILL using bentonite	
LOCATION SKETCH/COMMENTS COC #: LE04172014-02H			

Recorded By

G. Neutzling

Date 4/17/14

QA By

[Signature]

Date

5/5/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1104
SVP162307

PROJECT Coldwater Creek

INSPECTOR: *G. Neutzling*

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	0	Clayey SILT, med brown, little v. fine sand, low plasticity, moist - M.L.	73/7801			SVP162307 0757 Is. Th gamma spec		
	0.5		67/7697			SVP162308 0758 Is. Th gamma spec		
	1.5		56/7662			0800		
	2	Borehole terminated	60/7735			Archive 0801 Is. Th gamma spec		Archive Submitted 4/17/14 SVP174883 5/26/15 PR
	2							(soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By

G. Neutzling

Date 4/17/14

QA By

[Signature]

Date

5/5/14

HTRW DRILLING LOG		DISTRICT St. Louis USACE		HOLE NUMBER SVP162318	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 1109 (systematic auger) soil			
5. NAME OF DRILLER: Adam Queen / Antonio Martinez / David Conner		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES: Q8 12-15-14 E 8649456 N1075606595			
Meter - Background		9. SURFACE ELEVATION N/A			
44-9 A - 43 cpm		10. DATE STARTED 4/17/14		11. DATE COMPLETED: 4/17/14	
44-10 I - 756 cpm					
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC		RAD SAMPLES	
N/A		N/A		2	
22. DISPOSITION OF HOLE		BACKFILLED		MONITORING WELL	
Backfill using bentonite		w/bentonite		N/A	
LOCATION SKETCH/COMMENTS		23. SIGNATURE OF INSPECTOR: Gary Neutzling			
COC #: LE84172014-02H		SCALE: None			

Recorded By G. Neutzling Date 4/17/14 QA By [Signature] Date 5/5/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1109
SVP162318


SHEET 2 of 2

PROJECT Coldwater Creek		INSPECTOR:					REMARKS	
USCS	Depth (ft bgs)	449 NAI	PID	Recovery	Analytical Sample	Blow Counts		
	0	48	-	-	SVP162318 0808 Foot gamma Spec			
	0.5	66	-	-	0811			
	1	59	-	-	0814		Clay	
	1.5	66	-	-	SVP162319 0812 Foot gamma Spec			
	2	Borehole terminated						(Soil)
	5							
	6							
	7							
	8							
	9							
	10							

Recorded By G. Neutzling Date 4/17/14 QA By [Signature] Date 5/5/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162325	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION # 1113 (systematic annuq) soil			
5. NAME OF DRILLER Adam Queen / Antonio Martinez / David Guyan		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES 51 0812-15-14 E 864945 N 1075668 S2			
9. SURFACE ELEVATION N/A		10. DATE STARTED: 4/17/14 11. DATE COMPLETED: 4/17/14			
12. OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
13. DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES N/A		DISTURBED		UNDISTURBED	
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC	METALS	RAD SAMPLES	QA/QC SAMPLES
		N/A	N/A	4	19 out of 20
22. DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED w/bentonite	MONITORING WELL N/A	OTHER (SPECIFY) N/A	23. SIGNATURE OF INSPECTOR <i>[Signature]</i>
19. TOTAL NUMBER OF CORE BOXES N/A		21. TOTAL CORE RECOVERY N/A			

LOCATION SKETCH/COMMENTS
COC #: **LE04172014-02H**



Recorded By *[Signature]* Date **4/17/14** QA By *[Signature]* Date **5/5/14**

HTRW DRILLING LOG (Continuation Sheet)


HOLE NUMBER **1113**
SVP162325

PROJECT: Coldwater Creek		INSPECTOR: <i>[Signature]</i>				SHEET 2 of 2		
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	1	Clayey SILT, medium brown, little v. fine sand, low plastic, moist - ML	51/7594	-	-	SVP162325-0821	-	Collected 08/02/14 soil samples SVP162325-1 SVP162325-2
	15		52/7544	-	-	SVP162326-0823	-	
	52		52/7100	-	-	0825	-	
	2	Silty CLAY, medium brown, little to trace v. fine sand, low plasticity, moist - CL - becomes mottled by light brown below about 2 ft	52/7303	-	-	0828	-	CLAY
	3		55/7417	-	-	0835	-	
	4		62/7406	-	-	0837	-	
	5		62/7461	-	-	SVP162327-0838	-	
	6		51/7486	-	-	0839	-	
	7		61/7184	-	-	0842	-	
	8		56/7248	-	-	0845	-	
	9		58/7465	-	-	0847	-	
	10		67/7420	-	-	SVP162328-0844	-	
	11	Borehole terminated						soil

Recorded By *[Signature]* Date **4/17/14** QA By *[Signature]* Date **5/5/14**

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP/62333	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek			4. LOCATION: # 1117 (systematic array)		
5. NAME OF DRILLER: Adam Queen / Antonio Martinez / David Guyan			6. MANUFACTURERS DESIGNATION OF DRILL: N/A		
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		8. HOLE COORDINATES			
Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		Q 8 12-15-14 E 864945 N 1075730 19			
9. SURFACE ELEVATION: N/A		10. DATE STARTED: 4/17/14			
11. DATE COMPLETED: 4/17/14		12. OVERBURDEN THICKNESS: N/A			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
DISTURBED		UNDISTURBED		19. TOTAL NUMBER OF CORE BOXES: N/A	
20. SAMPLES FOR CHEMICAL ANALYSIS		RAD SAMPLES		QA/QC SAMPLES	
N/A		2		1 set of 2	
21. TOTAL CORE RECOVERY: N/A		ARCHIVE SAMPLE		1	
22. DISPOSITION OF HOLE		OTHER (SPECIFY)		23. SIGNATURE OF INSPECTOR	
Backfill using bentonite		N/A		Barry Neutzling	

LOCATION SKETCH/COMMENTS: Soil Sample 4/17/14
COC #: LE04172014-02H




Recorded By: S. Neutzling Date: 4/17/14 QA By: T. [Signature] Date: 5/5/14

HTRW DRILLING LOG (Continuation Sheet)				HOLE NUMBER 1117 SVP 162333		SHEET 2 of 2	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling		449		NAI	
Depth (ft bgs)		Description of Materials		Recovery		Analytical Sample	
0		SILT, med brown, some clay, little to some v. fine sand, low plasticity, slightly moist - ML		51		SVP162333	
0.5				55		0855	
1				7513		Iso Th gamma spec	
2				62		SVP162334	
2.5				55		0859	
3				7303		Iso Th gamma spec	
4		Borehole terminated				Refusal @ 1 1/2 ft offset 1 ft N.	
5						(soil)	
6							
7							
8							
9							
10							

Recorded By: S. Neutzling Date: 4/17/14 QA By: T. [Signature] Date: 5/5/14

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP162355	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 1129 (systematic auger) Soil			
5. NAME OF DRILLER Adam Queen / Antonio Martinez / David Gayan		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864945 N1075854			
Meter - Background 44-9 A - 43cpm 44-10 I - 7561cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 4/17/14 11. DATE COMPLETED 4/17/14			
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
14. TOTAL DEPTH OF HOLE 6.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY) N/A		18. GEOTECHNICAL SAMPLES N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		DISTURBED		UNDISTURBED	
21. TOTAL CORE RECOVERY: N/A		19. TOTAL NUMBER OF CORE BOXES N/A		22. DISPOSITION OF HOLE	
Backfill using bentonite		w/bentonite		N/A	



Recorded By *S. Neutzling* Date *4/17/14* QA By *[Signature]* Date *5/5/14*

HTRW DRILLING LOG (Continuation Sheet)		HOLE NUMBER 1129 SVP162355	
PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling	
SHEET 2 OF 2		REMARKS	
USCS	Depth (ft bgs)	Description of Materials	449 NAI PID Recovery Analytical Sample Blow Counts
0	59/7409	Clayey SILT, medium brown, little v. fine sand, low plasticity, moist - ML	SVP162355 0919 Iso Th gamma spec
1	60/7551		SVP162356 0921 Iso Th gamma spec
2	55/7390		0923
3	56/7500		0924
4	59/7562		0920
5	60/7389		0931
6	54/7463		0933
7	63/7631	SILT, brown mottled by light brown, some clay, little v. fine sand, low plasticity, slightly moist - ML	SVP162357 0935 Iso Th gamma spec
8	60/7604		0937
9	59/7590		0939
10	69/7481		SVP162358 0940 Iso Th gamma spec
11	60/7526		Archive 0941 Iso Th gamma spec
12	Borehole terminated		
13	Soil		
14	JMN 4/17/14		

Recorded By *S. Neutzling* Date *4/17/14* QA By *[Signature]* Date *5/5/14*

59

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER SVP 162296	
1. COMPANY NAME Leidos		2. DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3. PROJECT Coldwater Creek		4. LOCATION # 1099 (systematic array) soil			
5. NAME OF DRILLER Adam Queen/Matt Dostal		6. MANUFACTURERS DESIGNATION OF DRILL N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES E 864945 N1075482			
Meter - Background 44-9 F - 45 cpm 44-10 E - 8084 cpm		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 4/23/14 11. DATE COMPLETED 4/23/14			
13. DEPTH DRILLED INTO ROCK N/A		15. DEPTH GROUNDWATER ENCOUNTERED N/A			
14. TOTAL DEPTH OF HOLE 2.0 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
18. GEOTECHNICAL SAMPLES: N/A		19. TOTAL NUMBER OF CORE BOXES N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC N/A		METALS N/A	
22. DISPOSITION OF HOLE Backfill using bentonite		RAD SAMPLES 2		QA/QC SAMPLES 1 set of 2	
23. SIGNATURE OF INSPECTOR G. Neutzling		ARCHIVE SAMPLE 0		21. TOTAL CORE RECOVERY: N/A	
LOCATION SKETCH/COMMENTS Soil 4/23/14 COGN: LE04242014-01H					

Recorded By G. Neutzling Date 4/23/14 QA By [Signature] Date 5/5/14

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1099
SVP 162296

PROJECT: Coldwater Creek		INSPECTOR: G. Neutzling				SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts
0	55/8372	SILT, med brown, little clay, little v. fine sand, low plasticity, moist (Fill)				SVP162296 1436 Iso Th gamma spec	Collect QC/QA Soil samples SVP162296-1 SVP162296-2
0.5	50/8328					1437	
1	57/8304					1439	
1.5	64/8102	SILT, brown, little clay, little fine sand, trace of asphalt piece, trace gravel, low plasticity, slightly moist (Fill)				SVP162297 1434 Iso Th gamma spec	somewhat dry asphalt piece of rock
2.0		Borehole terminated					Soil
5							
6							
7							
8							
9							
10							

Recorded By G. Neutzling Date 4/23/14 QA By [Signature] Date 5/5/14

HTRW DRILLING LOG

DISTRICT: St. Louis USACE

HOLE NUMBER 1774 SVP 171301

1. COMPANY NAME: Leidos

2. DRILL SUBCONTRACTOR: Leidos

3. PROJECT: Coldwater Creek

4. LOCATION # 1774 (bounding loc.)

5. NAME OF DRILLER: T. Keeton

6. MANUFACTURERS DESIGNATION OF DRILL: N/A

7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve

8. HOLE COORDINATES N: 1073683 E: 864897

9. SURFACE ELEVATION: N/A

10. DATE STARTED: 5-6-14

11. DATE COMPLETED: 5-6-14

12. OVERBURDEN THICKNESS: N/A

13. DEPTH DRILLED INTO ROCK: N/A

14. TOTAL DEPTH OF HOLE: 1.0 ft bgs.

15. DEPTH GROUNDWATER ENCOUNTERED: N/A

16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A

17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A

18. GEOTECHNICAL SAMPLES: N/A

19. TOTAL NUMBER OF CORE BOXES: N/A

20. SAMPLES FOR CHEMICAL ANALYSIS: VOC, METALS, RAD SAMPLES, QA/QC SAMPLES, ARCHIVE SAMPLE


21. TOTAL CORE RECOVERY: N/A

22. DISPOSITION OF HOLE: BACKFILLED, MONITORING, OTHER (SPECIFY)

23. SIGNATURE OF INSPECTOR: [Signature]

Backfill using bentonite w/bentonite N/A N/A

LOCATION SKETCH/COMMENTS COC#: LE05072014-014 SCALE: None



HTRW DRILLING LOG

DISTRICT: St. Louis USACE

HOLE NUMBER 1776 SVP 171305

1. COMPANY NAME: Leidos

2. DRILL SUBCONTRACTOR: Leidos

SHEET 1 OF 2

3. PROJECT: Coldwater Creek

4. LOCATION: # 1776 (boundary loc.)

5. NAME OF DRILLER: T. Keaton

6. MANUFACTURERS DESIGNATION OF DRILL: N/A

7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT: Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve

8. HOLE COORDINATES: N: 1073617 E: 864936

9. SURFACE ELEVATION: N/A

10. DATE STARTED: 5-6-14

11. DATE COMPLETED: 5-6-14

12. OVERBURDEN THICKNESS: N/A

15. DEPTH GROUNDWATER ENCOUNTERED: N/A

13. DEPTH DRILLED INTO ROCK: N/A

16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A

14. TOTAL DEPTH OF HOLE: 1.0 ft bgs.

17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A

18. GEOTECHNICAL SAMPLES: N/A

19. TOTAL NUMBER OF CORE BOXES: N/A


20. SAMPLES FOR CHEMICAL ANALYSIS: VOC, METALS, RAD SAMPLES, QA/QC SAMPLES, ARCHIVE SAMPLE

21. TOTAL CORE RECOVERY: N/A

22. DISPOSITION OF HOLE: BACKFILLED, MONITORING, OTHER (SPECIFY)

23. SIGNATURE OF INSPECTOR

Backfill using bentonite w/bentonite N/A N/A



Recorded By [Signature] Date 5-6-14 QA By [Signature] Date 5-12-14

HTRW DRILLING LOG (Continuation Sheet)

PROJECT: Coldwater Creek

INSPECTOR: [Signature]

HOLE NUMBER 1776 SVP 171305

SHEET 2 of 2

USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
		Brown clayey silt Low plasticity, Moist Trace V.F. sand Trace roots	68 8012 6858 8261			SVP171305 1319 SVP171306 1320		0-0.5' 0.5-1.0' (Soil)
1		Borehole Terminated						
2								
3								
4								
5								
6								
7								
8								
9								
10								

COL#: LG 05072014-014


Recorded By [Signature] Date 5-6-14 QA By [Signature] Date 5-12-14

69

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER 1771 SVP167117	
1. COMPANY NAME: Leidos		2. DRILL SUBCONTRACTOR: Leidos		SHEET 1 OF 2	
3. PROJECT: Coldwater Creek		4. LOCATION: # 1771 (bounding log)			
5. NAME OF DRILLER: T. Keeton		6. MANUFACTURERS DESIGNATION OF DRILL: N/A			
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES N: 1073671 E: 864954			
Meter - Background 44-9 F - 46 44-10 I - 7690		9. SURFACE ELEVATION N/A			
12. OVERBURDEN THICKNESS N/A		10. DATE STARTED: 5-6-14		11. DATE COMPLETED: 5-6-14	
13. DEPTH DRILLED INTO ROCK: N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
14. TOTAL DEPTH OF HOLE: 1.5 ft bgs		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED: N/A			
17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A		18. GEOTECHNICAL SAMPLES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		21. TOTAL CORE RECOVERY: N/A		23. SIGNATURE OF INSPECTOR: <i>[Signature]</i>	
22. DISPOSITION OF HOLE Backfill using bentonite		21. TOTAL CORE RECOVERY: N/A		23. SIGNATURE OF INSPECTOR: <i>[Signature]</i>	

LOCATION SKETCH/COMMENTS **COC #: LE05072014-014**


SCALE: None

Recorded By *[Signature]* Date **5-6-14** QA By *[Signature]* Date **5-12-14****HTRW DRILLING LOG (Continuation Sheet)**HOLE NUMBER **1771**
SVP167117

PROJECT: Coldwater Creek		INSPECTOR: <i>[Signature]</i>		SHEET 2 of 2	
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery
		Mad. brown clay MD 5-6-14 DISCARDED			
1		Mad. brown clayey silt low plasticity, Moist Trace V.F. sand Trace roots (ML)	66 8195 59 8178		SVP171336 1327 ARCHIVE 1328
		Borehole Terminated			Soil
2					
3					
4					
5					
6					
7					
8					
9					
10					

COC #: LE05072014-014Recorded By *[Signature]* Date **5-6-14** QA By *[Signature]* Date **5-12-14**

HTRW DRILLING LOG				DISTRICT: St. Louis USACE				HOLE NUMBER 1778 SVP 171309	
1. COMPANY NAME: Leidos				2. DRILL SUBCONTRACTOR Leidos					
3. PROJECT: Coldwater Creek				4. LOCATION # 1778 (bounding loc.)					
5. NAME OF DRILLER: T. Keeton				6. MANUFACTURERS DESIGNATION OF DRILL N/A					
7. SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT		Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8. HOLE COORDINATES N: 1073716 E: 864999					
Meter - Background				9. SURFACE ELEVATION N/A					
44-9 F - 40				10. DATE STARTED: 5-6-14				11. DATE COMPLETED 5-6-14	
44-10 I - 7690									
12. OVERBURDEN THICKNESS N/A				15. DEPTH GROUNDWATER ENCOUNTERED: N/A					
13. DEPTH DRILLED INTO ROCK: N/A				16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A					
14. TOTAL DEPTH OF HOLE 4.0 ft. bgs.				17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A					
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED		19. TOTAL NUMBER OF CORE BOXES: N/A			
20. SAMPLES FOR CHEMICAL ANALYSIS		VOC	METALS		RAD SAMPLES	QA/QC SAMPLES	ARCHIVE SAMPLE	21. TOTAL CORE RECOVERY N/A	
N/A		N/A	N/A		6	1 QA / 1 QC	0		
22. DISPOSITION OF HOLE		BACKFILLED	MONITORING		OTHER (SPECIFY)	23. SIGNATURE OF INSPECTOR			
Backfill using bentonite		w/bentonite	N/A		N/A	[Signature]			
LOCATION SKETCH/COMMENTS COC #: LE05012014-0114				SCALE: None					



Recorded By MD Date 5-6-14 QA By I Date 5-12-14

HTRW DRILLING LOG (Continuation Sheet)						HOLE NUMBER 1778 SVP 171309	
PROJECT Coldwater Creek			INSPECTOR: <i>NTD</i>				SHEET 2 of 2
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts Remarks
		Brown clayey silt, Low plasticity, Moist, Trace V.F. sand, trace carb (ML)	59 8185			SVP171309 1345	QA/QC 0-0.5'
1		DISCARDED					
2		Darker brown clayey silt, Low plasticity, Moist, Some V.F. sand (ML)	81 8002			SVP171310 1347	1.5-2.0'
			56 7833			SVP171311 1350	2.0-2.5'
3		Trace more clay content	59 7885			SVP171312 1352	2.5-3.0'
			57 7818			SVP171313 1356	3.0-3.5'
4			65 8158			SVP171314 1358	3.5-4.0'
		Borehole Terminated					(Soil)
5							
6							
7							
8							
9							
10							

MD
5-6-14


COC #: LE05072014-014

Recorded By MDX Date 5-6-14 QA By 1 MDX Date 5-12-14

75

HTRW DRILLING LOG		DISTRICT: St. Louis USACE		HOLE NUMBER 1763 SVP 167103	
1 COMPANY NAME: Leidos		2 DRILL SUBCONTRACTOR Leidos		SHEET 1 OF 2	
3 PROJECT: Coldwater Creek		4 LOCATION # 1763 (bounding box)			
5 NAME OF DRILLER: T. Keeton		6 MANUFACTURERS DESIGNATION OF DRILL N/A			
7 SIZES AND TYPES OF DRILLING AND SAMPLING EQUIPMENT Stainless Steel (ss) bowl, ss trowel, with ss hand auger 3in ID or ss sediment sampler with plastic sleeve		8 HOLE COORDINATES N: 1073753 E: 864989			
Meter - Background 44-9 F - 40 44-10 I - 7890		9 SURFACE ELEVATION N/A			
		10. DATE STARTED: 5-6-14		11. DATE COMPLETED: 5-6-14	
12 OVERBURDEN THICKNESS N/A		15. DEPTH GROUNDWATER ENCOUNTERED: N/A			
13 DEPTH DRILLED INTO ROCK N/A		16. DEPTH TO WATER AND ELAPSED TIME AFTER DRILLING COMPLETED N/A			
14 TOTAL DEPTH OF HOLE 4.5 ft bgs.		17. OTHER WATER LEVEL MEASUREMENTS (SPECIFY): N/A			
18. GEOTECHNICAL SAMPLES: N/A		DISTURBED		UNDISTURBED	
20 SAMPLES FOR CHEMICAL ANALYSIS N/A		VOC		METALS	
		RAD SAMPLES		QA/QC SAMPLES	
		ARCHIVE SAMPLE		21. TOTAL CORE RECOVERY: N/A	
22 DISPOSITION OF HOLE Backfill using bentonite		BACKFILLED		MONITORING	
		w/bentonite		N/A	
		OTHER (SPECIFY)		23. SIGNATURE OF INSPECTOR	

LOCATION SKETCH/COMMENTS COL#: LE05072014-014 SCALE: None



Recorded By [Signature] Date 5-6-14 QA By [Signature] Date 5-12-14

76

HTRW DRILLING LOG (Continuation Sheet)

HOLE NUMBER 1763
SVP 167103

PROJECT: Coldwater Creek		INSPECTOR: [Signature]		SHEET 2 of 2				
USCS	Depth (ft bgs)	Description of Materials	449 NAI	PID	Recovery	Analytical Sample	Blow Counts	Remarks
	1	DISCARDED						
	2							
	3							
	4	Brown clayey silt low plasticity, Moist (ML) Some V.F. sand	75 8119 71 8062			SVP171334 1403 SVP171335 1405		3.5-4.0' 4.0-4.5'
	5	Borehole Terminated						Soil
	6	[Diagonal line across the grid]						
	7							
	8							
	9							
	10							

Recorded By [Signature] Date 5-6-14 QA By [Signature] Date 5-12-14