



HEAD CUT ON BANK CAUSED BY HIGH WATER RESSION IN SPRING 2002 MILE 89.6



DEPOSITION OF COARSE MATERIAL AT MILE 89.6



**U.S. ARMY ENGINEER DISTRICT, ST. LOUIS
CORPS OF ENGINEERS
ST. LOUIS, MO**

PREPARED BY: M. RODGERS
CHECKED BY: R. DAVINROY

**KASKASKIA RIVER
BANK EROSION STUDY**



SCOUR/DEPOSITION MILE 89.6

PLATE NO.

Plot Date: 9/02

37