



Photograph of dredged pond and riprap stabilization placed along shoreline. Photograph is facing northwest. Note berm on far right hand side of the photograph.



Photograph of the 0.37-acre cleared forested wetland, facing northeast.



Photograph of the landward side of the berm created north of the pond within former wetland, facing east.



Photograph of spoil material stockpile within emergent wetland (Area B), facing west.